Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011351/DGS3Q2

**Date:** 08/01/2021

**REFERENCE** 

Vehicle No:

Handling Insurer: India International Insurance Pte

Policy No:

D20MPC0002115

Claimant

GBD7304H

Ltd

Insured Vehicle No :

SKM6010H

Date of Loss:

19/10/2020

Nature of Claim: TP

Claim No: MPC2020D0002149

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBD7304H

 Make & Model:
 TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)
 Engine No:
 1KD2451147

 Reg. Date:
 27/03/2015 (Man. Year: 2014)
 Chassis No:
 KDY2318017479

 Colour:
 White
 Odometer:
 215204 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185R15C Rear Tyre Size: 155R13C(D)
Front Left Side: Nexen 5 mm Rear Left Side: Condor 5/5 mm
Front Right Side: Nexen 5 mm Rear Right Side: Condor 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,580.58	1,906.62	7,673.96	80.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	1,150.00	4,800.00	80.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,530.58	3,056.62	12,473.96	80.32
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	15,530.58	2,400.00	13,130.58	84.55
+ GST 7.00/7.00% (S\$)	1,087.14	168.00	919.14	84.55
Nett Amount (S\$)	16,617.72	2,568.00	14,049.72	84.55
+ Car Rental (5.0 x S\$6	60.00/day) (S\$)	300.00		
+ Doc/Search Fee (S\$)  Nett Liability (S\$)  Global Sum Settlement (S\$)		36.45		
		2,904.45		
		2,900.00		

**INSPECTION** 

Date of Assignment: 20/10/2020

Date Inspected: 20/10/2020 Inspected At: JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A,, #03-

08 AMK AutoPoint Singapore 568047 Adjuster Report Page 2 of 4

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## **REPAIR DETAILS**

Reference				
Part Source:		(Last Synchronised: 03 Dec 2020)		
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	: (Unsubmitted, no print-code for GBD7304H)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,679.06 FL	*-FL
2	1		*REAR TAILGATE HINGE (4 Pcs)	O/s Bent/N/s Not Necessary	410.84 FL	*205.42 FL
3	1		*REAR TAILGATE LOCK RH	Bent	217.31 FL	*217.31 FL
4	1		*REAR TAILGATE LOCK BRACKET RH	No such part	97.20 FL	*- FL
5	1		*REAR TAILGATE STOPPER RH	Serviceable	51.78 FL	*-FL
6	1		*REAR TAILGATE STOPPER BRACKET RH	Bent	96.27 FL	*96.27 FL
7	1		*REAR SIDE GATE RH	Not Necessary	1,854.72 FL	*- FL
8	1		*TAIL LAMP RH	Broken	393.70 FL	*393.70 FL
9	1		*TAIL LAMP PANEL RH	Bent	89.96 FL	*89.96 FL
10	1		*TAIL LAMP REFLECTOR RH	Broken	284.50 FL	*284.50 FL
11	1		*REAR FLOOR PANEL	Not Necessary	2,880.90 FL	*- FL
12	2		*CHASSIS BRACKET	Not Necessary	314.52 FL	*- FL
13	1		*REAR END PANEL	Dented	843.20 FL	*584.30 FL
14	1		*REAR EXHAUST PIPE	Bent	1,489.92 FL	*570.70 FL
15	1		*REAR EXHAUST MOUNTING	Not Necessary	194.56 FL	*-FL
16	1		*REAR NO PLATE LAMP	Not Necessary	169.00 FL	*- FL
17	1		*REAR NUMBER PLATE	Broken	40.00 FS	*20.00 FS
18	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*-FS
19	1		*REAR STEP BAR	No such part	300.00 FS	*-FS
20	1		*70KM STICKER	Necessary	30.00 FS	*15.00 FS
21	1		*DYNA STICKER	Necessary	400.00 FS	*20.00 FS
22	1		*13PAX STICKER	Necessary	30.00 FS	*20.00 FS
23	1		*1500KG STICKER	Not Necessary	100.00 FS	*-FS
24	1		*NAGANO TOYOTA STICKER	Not Necessary	200.00 FS	*-FS
25 F=Fra	1 anchise	part. S=S	*CAUTION SIGN STICKER SpcNett. L=ListItemDisc.	Not Necessary	100.00 FS	*-FS
			L	Sub Total (S¢)	12 247 44	2 517 16

Sub Total (\$\$) 12,347.44 2,517.16
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,766.86 610.54

**Total Parts (S\$)** 9,580.58 1,906.62

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RNR REAR METAL DECK TO FACILITATE REPAIRS	New	1,800.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,600.00	450.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	60.00
	Gross Labour Cost (S\$)		5,950.00	1,150.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >