

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Oct 2020 10:59 Edit Reg		20 Oct 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SLR5195B	Date of Loss:	17/10/2020 00:00 - :59 [38 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA3011Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Excel Motor (HQ) BLK 5032 Ang Mo Kio Industrial Park 2, #01-297, 569535 Ang Mo Kio - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLR5195B**
[SHA3011Z]
TP

-
Oct 17 2020 12:00AM

[-]
Excel Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/10/20 17:01	Odometer Reading	Load JPG	☒
2	20/10/20 17:01	Chassis Number	Load JPG	☒
3	20/10/20 17:01	General View	Load JPG	☒
4	20/10/20 17:01	General View	Load JPG	☒
5	20/10/20 17:01	General View	Load JPG	☒
6	20/10/20 17:01	General View	Load JPG	☒
7	20/10/20 17:01	General View	Load JPG	☒
8	20/10/20 17:01	General View	Load JPG	☒
9	20/10/20 17:01	General View	Load JPG	☒
10	20/10/20 17:01	General View	Load JPG	☒
11	20/10/20 17:01	General View	Load JPG	☒
12	20/10/20 17:01	General View	Load JPG	☒
13	20/10/20 17:01	General View	Load JPG	☒
14	20/10/20 17:01	General View	Load JPG	☒
15	22/10/20 16:11	Photo After Spray	Load JPG	☒
16	22/10/20 16:11	Photo After Spray	Load JPG	☒
17	22/10/20 16:11	Photo After Spray	Load JPG	☒
18	22/10/20 16:11	Photo After Spray	Load JPG	☒
19	22/10/20 16:11	Photo After Spray	Load JPG	☒
20	22/10/20 16:11	Photo After Spray	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/10/20 11:23	EMAIL FROM III TO CONDUCT SURVEY	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/10/20 08:39	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20011354/KSD3S2**Date:** 28/10/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLR5195B**Insured Vehicle No :** SHA3011Z

Date of Loss: 17/10/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLR5195B**

Make & Model: HONDA HR-V, 1.5 (A)

Engine No: L15B4532405

Reg. Date: 17/08/2017 (Man. Year: 2017)

Chassis No: JHMRU1830GX202405

Colour: Metallic Dark Blue

Odometer: 64272 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/10/2020

Date Inspected: 20/10/2020 Inspected At:

Excel Motor (HQ)

BLK 5032 Ang Mo Kio Industrial Park 2, #01-297

Singapore 569535

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

10/28/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2020)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR5195B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >