4/10/2021 Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III20011355/QBA3Q2

Date:

10/04/2021

**REFERENCE** 

Handling Insurer:

India International Insurance Pte Ltd

Policy No:

MCOM0015

**Claimant Vehicle** 

SMB1568H

Insured Vehicle No:

SHB4261G

No: Date of Loss:

15/10/2020

Nature of Claim:

ΤP

Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Rea No:

SMB1568H

Make & Model:

MAN NL320F (A22), 10.5 D (M) 23/12/2014 (Man. Year: 2014)

Engine No: Chassis No: Odometer:

50339082603920

WMAA22ZZ6F7002527

Reg. Date: Colour:

Multi-colour

**Engine Capacity:** Market Value/New Car Price:

10518 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable): Yes

511930 km

Handbrake (Serviceable):

Yes **Engine Modification:**  No

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: Front Left Side:

275/70 R22.5 Falken 6 mm Rear Tyre Size: Rear Left Side:

275/70 R22.5 Falken 6 mm

Front Right Side:

Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,140.00	1,946.00	194.00	9.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,206.00	1,241.00	965.00	43.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,346.00	3,187.00	1,159.00	26.67
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	4,346.00	2,400.00	1,946.00	44.78
Global S	um Settlement (S\$)	0.00		

**INSPECTION** 

Date Inspected:

Date of Assignment:

20/10/2020

20/10/2020 Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair:

2.0 days

Manager:

CHUA ZHEN LI

Adjuster: OI SUN PIN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/10/2021 Adjuster Report

#### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Apr 2021)

Parts: N/A MAN NL320F (A22) 10.5 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMB1568H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRAME EXIT DOOR FOR MAN A22 BUS	Scratched	440.00 F	*440.00 FL
2	1		*RUBBER,EXIT DOOR :FOR MAN A22 BUS	Cut	750.00 F	*750.00 FL
3	1		*RUBBER,EXIT DOOR :FOR MAN A22 BUS	Cut	750.00 F	*750.00 FL
4	1		*SMRT STICKER	Necessary	200.00 FS	*200.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,140.00	2,140.00
			- List Item Discount on L Items 0	.00/10.00% (S\$)	0.00	194.00
				Total Parts (S\$)	2,140.00	1,946.00
			Report was unsubmitted during this prin	t-out		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	616.00	446.00
	Gross Labor	ur Cost (S\$)	2,206.00	1,241.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >