



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205400

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 01/09/2022  
Reference CC6/CTI20011360/Kea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. GBF 4764Y  
Insured Veh. GBC 4426P  
Claim No. SNM20D203935/C02  
Policy No. DMCVSN3084771900  
Accident Date 28/09/2020  
Inspection Date 15/10/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20011360/Kea3q2 Date: 01/09/2022 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBC 4426P	<b>Veh. Inspected</b>	GBF 4764Y
	<b>Policy No.</b>	DMCVSN3084771900	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	SNM20D203935/C02	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	15/10/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA HIACE (M)	<b>c.c</b>	2982
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	JTFHT02P400207471	<b>Colour</b>	WHITE
	<b>Odometer</b>	94596 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195 R15X8	BEARWAY	9 mm
	<b>L/H Front Tyre</b>	195 R15X8	BEARWAY	9 mm
	<b>R/H Rear Tyre</b>	195 R15X8	BEARWAY	9 mm
	<b>L/H Rear Tyre</b>	195 R15X8	BEARWAY	9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	28/09/2020	<b>Inspection Date</b>	15/10/2020
	<b>Survey held at</b>	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4764Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	452.10	-
1	FRONT BUMPER LH SIDE RETAINER	SERVICEABLE	191.30	-
1	FRONT BUMPER INNER REINFORCEMENT	TO REPAIR SEE LABOUR	364.40	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	40.00	-
1	LH HEADLAMP	CRACKED	748.10	748.10
1	FRONT LH CORNER PANEL	BENT/ BUCKLED	258.10	258.10
1	FRONT GRILLE ASSY	SERVICEABLE	580.80	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	756.60	-
1	FRONT BONNET CENTRE 'TOYOTA' LOGO	NECESSARY	66.09	66.09
	LESS 25% DISCOUNT		-864.37	-268.07
			2,593.12	804.22
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF FRONT BUMPER INNER REINFORCEMENT ,FRONT BUMPER AND FRONT BONNET .		700.00	350.00
	TO PUTTY AND SPRAY PAINTINGS CHARGES.		1,000.00	600.00
	TO CHECK WIRING & LIGHTINGS.		40.00	20.00
	TO REMOVE,REFIT A/C CONDENSER ,RADIATOR AND ETC.	NOT NECESSARY	150.00	-
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	80.00	-
			1,970.00	970.00
	<b>GRAND TOTAL</b>		<b>4,563.12</b>	<b>1,774.22</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,774.22</b>

Report Ref No. CC6/CTI20011360/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 4764Y

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. GBF 4764Y**

**RE-INSPECTION**

