

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011363/AVF3E2

Date: 23/06/2021

REFERENCE

Insured/Claimant:	LIM JIN MIN	Policy No:	2070111152		
Date of Loss:	18/10/2020	Nature of Claim:	OD	Claim No:	4521330402SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCW999L		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	DEM023855
Reg. Date:	24/07/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF4XLN013645
Colour:	White	Odometer:	3800 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,392.00	7,562.88	3,829.12	33.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,732.00	9,977.00	4,755.00	32.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,124.00	17,539.88	8,584.12	32.86
+ GST 7.00/7.00% (S\$)	1,828.68	1,227.79	600.89	32.86
Nett Amount (S\$)	27,952.68	18,767.67	9,185.01	32.86

INSPECTION

Date of Assignment:	20/10/2020		
Date Inspected:	20/10/2020	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,122.00 FS	*1,697.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	164.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	246.00 FS	*196.40 FS
4	1		*REAR BUMPER BRACKET-LH	Not Necessary	201.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR-LH INNER/OUTER	Not Necessary	86.00 FS	*- FS
6	1		*LED TAIL LIGHT-LH	Cut	1,008.00 FS	*806.40 FS
7	1		*TALL LIGHT TRIM-LH	Not Necessary	30.00 FS	*- FS
8	1		*EXHAUST TAIL PIPE TRIM-LH	Not Necessary	350.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-INNER	Not Necessary	44.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION-OUTER	Damaged	22.00 FS	*17.52 FS
11	1		*REAR FENDER-LH	Dented	2,644.00 FS	*2,115.20 FS
12	1		*REAR WINDSCREEN	Necessary	1,141.00 FS	*912.80 FS
13	1		*SIDE WINDOW-LH	Necessary	648.00 FS	*518.40 FS
14	1		*PRIMER	Necessary	19.00 FS	*14.96 FS
15	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	237.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	138.00 FS	*- FS
17	1		*REAR ALUMINIUM RIM-LH	Not Necessary	692.00 FS	*- FS
18	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
20	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
21	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
22	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*SUNDRIES	Necessary	300.00 FS	*27.60 FS
25	1		*REAR BUMPER SECURING STRIP	Necessary	220.00 FS	*176.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,392.00 7,562.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO RENEW 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO DISMANTLE AND RENEW REAR BUMPER.CUT OUT AND WELD LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,900.00	3,000.00
8	TO RESPRAY REAR BUMPER,LHS REAR FENDER,DOOR ENTRANCES,LHS SILL PANEL,ROOF CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,000.00	2,475.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			14,732.00	9,977.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >