

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20011364/ATF3E2

**Date:** 18/03/2021

### REFERENCE

Insured/Claimant: DINESH KUMAR S/O U NAGARAJU  
Date of Loss: 15/10/2020

Policy No: 1800033993  
Nature of Claim: OD Claim No: 7765173391SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX7340D**  
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZ619681  
Reg. Date: 09/04/2018 (Man. Year: 2017) Chassis No: WAUZZZGAXJA050672  
Colour: Orange Odometer: 39729 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$93,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,393.00	12,099.84	11,293.16	48.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,052.00	5,552.00	4,500.00	44.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>33,445.00</b>	<b>17,651.84</b>	<b>15,793.16</b>	<b>47.22</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>32,445.00</b>	<b>16,651.84</b>	<b>15,793.16</b>	<b>48.68</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,271.15</b>	<b>1,165.63</b>	<b>1,105.52</b>	<b>48.68</b>
<b>Nett Amount (S\$)</b>	<b>34,716.15</b>	<b>17,817.47</b>	<b>16,898.68</b>	<b>48.68</b>

### INSPECTION

Date of Assignment: 20/10/2020

Date Inspected: 20/10/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 8.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,854.00 FS	*1,482.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Deformed	195.00 FS	*155.60 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/s Deformed	334.00 FS	*133.60 FS
5	2		*FRONT BUMPER END CAP - LH / RH	Not Necessary	68.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	296.00 FS	*236.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	154.00 FS	*- FS
8	2		*WHEEL SPOILER - LH / RH	Not Necessary	68.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	42.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,395.00 FS	*1,116.00 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	cracked	123.00 FS	*98.00 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	cracked	77.00 FS	*61.20 FS
13	1		*FRONT BUMPER CARRIER	cracked	679.00 FS	*543.20 FS
14	1		*FRONT BUMPER TOP COVER	Deformed	99.00 FS	*79.04 FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	35.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
17	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
18	1		*SIGNAL HORN - RH HIGH TONE	Not Necessary	180.00 FS	*- FS
19	1		*SPRING SHACKLE - RH	Not Necessary	31.00 FS	*- FS
20	1		*BONNET	Dented	2,757.00 FS	*2,205.60 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
22	2		*BONNET LID HINGE - LH / RH	Not Necessary	122.00 FS	*- FS
23	2		*BONNET STRIKER - LH / RH	Not Necessary	218.00 FS	*- FS
24	1		*BONNET SOUND ABSORBER	Not Necessary	217.00 FS	*- FS
25	1		*BONNET IMPACT PROTECTION - CENTRE / LH / RH (3 Pcs)	Necessary	90.00 FS	*70.48 FS
26	2		*FRONT FENDER INNER COVER - LH / RH	Not Necessary	32.00 FS	*- FS
27	1		*PLENUM CHAMBER COVER	Not Necessary	156.00 FS	*- FS
28	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
29	1		*BONNET RELEASE ELEMENT	Not Necessary	57.00 FS	*- FS
30	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
31	1		*HEADLIGHT MOUNTING - LH / RH	O/s cracked	234.00 FS	*93.60 FS
32	1		*LED HEADLIGHT - LH / RH	N/s Cut	9,718.00 FS	*3,887.20 FS
33	2		*LIFT CYLINDER - LH / RH	Not Necessary	282.00 FS	*- FS
34	1		*LIFT CYLINDER HOSE	Not Necessary	175.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE - LH / RH	O/s cracked	60.00 FS	*23.92 FS
36	1		*RADIATOR AIR GUIDE - UPPER CENTRE	cracked	22.00 FS	*17.04 FS
37	1		*LOCK CARRIER	cracked	983.00 FS	*786.40 FS
38	1		*READY MIX COOLANT	Necessary	91.00 FS	*72.32 FS
39	1		*AIRCON CONDENSER	bent	545.00 FS	*436.00 FS
40	2		*FRONT WHEEL COVER - LH / RH	Necessary	636.00 FS	*508.80 FS
41	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
42	1		*SUNDRIES	Necessary	300.00 FS	*16.96 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 23,393.00 12,099.84**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	800.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,250.00
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	2,500.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,052.00</b>	<b>5,552.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >