

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011365/UTF3E2  
Date: 06/01/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00048312000  
Claimant Vehicle No : SFY440K Insured Vehicle No : GBJ5389U  
Date of Loss: 17/10/2020 Nature of Claim: TP Claim No: SNM20D203914/C03/CHUAK

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFY440K  
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11BC9353  
Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: GF7W0601648  
Colour: Blue Odometer: 18104 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18  
Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm  
Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,097.00	6,791.00	3,306.00	32.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,700.00	4,110.00	4,590.00	52.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,797.00</b>	<b>10,901.00</b>	<b>7,896.00</b>	<b>42.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,315.79</b>	<b>763.07</b>	<b>552.72</b>	<b>42.01</b>
<b>Nett Amount (S\$)</b>	<b>20,112.79</b>	<b>11,664.07</b>	<b>8,448.72</b>	<b>42.01</b>

### INSPECTION

Date of Assignment: 30/12/2020  
Date Inspected: 20/10/2020 Inspected At: CYCLE & CARRIAGE.FULCO MOTOR DEALER PL  
NO.330 UBI ROAD 3  
SINGAPORE 408650  
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$1,433.00 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2021)
<b>Parts:</b>	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFY440K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE ASSY,RADIATOR	*Check	548.00 FS	*- FS
2	1		*COVER,UPR HEADLAMP S	*Check	50.00 FS	*- FS
3	1		*FACE,FR BUMPER	Distorted	859.00 FS	*859.00 FS
4	1		*CLIP,BUMPER (30 Pcs)	Necessary	120.00 FS	*120.00 FS
5	1		*LH BRACKET,FR BUMPER	Bent	18.00 FS	*18.00 FS
6	1		*RH BRACKET,FR BUMPER	Not Necessary	18.00 FS	*- FS
7	1		*COVER,FR BUMPER	Deformed	355.00 FS	*355.00 FS
8	1		*EXTENSION,FR BUMPER	Deformed	515.00 FS	*515.00 FS
9	1		*LH HEADLAMP ASSY	Cracked	1,938.00 FS	*1,938.00 FS
10	1		*SIDE UPR GARNISH,H/L	Grazed	48.00 FS	*48.00 FS
11	1		*UPR SIDE GARNISH,FR	Cracked	220.00 FS	*220.00 FS
12	1		*LWR SIDE GARNISH,FR	Scratched	112.00 FS	*112.00 FS
13	1		*LH GARNISH,FOG LAMP	Grazed	48.00 FS	*48.00 FS
14	1		*LH FR LAMP ASSY,FOG	*Check	345.00 FS	*- FS
15	1		*LH MOULDING,FR BUMP	Grazed	116.00 FS	*116.00 FS
16	1		*LH FENDER,FR	Buckled	688.00 FS	*688.00 FS
17	1		*LH MOULDING,FR WHEEL	Grazed	160.00 FS	*160.00 FS
18	1		*LH SHIELD,FR WHEELHO	Not Necessary	164.00 FS	*- FS
19	10		*CLIP,SPLASH SHIELD	Necessary	40.00 FS	*40.00 FS
20	1		*UPR PANEL,HEADLAMP S	Repair	182.00 FS	*- FS
21	1		*LH UPR PANEL,HEADLA	Repair	58.00 FS	*- FS
22	1		*REINFORCEMENT,FR BUM	*Check	490.00 FS	*- FS
23	1		*OUTLANDER 2019 BODY	Cracked	1,554.00 FS	*1,554.00 FS
24	1		*WHEEL,DISC	Serviceable	974.00 FS	*- FS
25	1		*225/55/18 TYRE	Serviceable	373.00 FS	*- FS
26	4		*COOLANT	Not Necessary	104.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>10,097.00</b>	<b>6,791.00</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DIAGNOSTIC/SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REMOVE & RE-INSTALL RADIATOR,AC CONDENSER TO FACILITATE REPLACEMENT OF FRONT SUPPORT PANEL.TO TOP UP AC GAS & COOLANT	New	180.00	0.00
4	TO REPLACE GRILLE,LH HEADLAMP,FRONT BUMPER,LHF FENDER,BGARNISH,MOULDINGS,BRACKETS,CLIPS,ETC-TO CUT & WELD,UPR & SIDE SUPPORT PANEL-TO REPAIR LHF DOOR.STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	4,200.00	1,500.00
5	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	2,940.00	1,680.00
6	TO REPLACE & RESPRAY BODY KIT (TO APPLY SEALANT KIT)	New	800.00	600.00
7	COMPUTERIZED WHEEL ALIGNMENT	New	180.00	0.00
8	WHEEL BALANCING (1 PC)(TO REPLACE RIM & TYRE)	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,700.00</b>	<b>4,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >