

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20011366/T1GS3Q2

Date: 12/05/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700069448
Claimant Vehicle No :	SBV8813D	Insured Vehicle No :	SLT2633M
Date of Loss:	17/10/2020	Nature of Claim:	TP
		Claim No:	9597829883SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBV8813D</b>		
Make & Model:	BMW 650I, 4.4 ABS D/AB 2WD DSC HID HUD INT/S (A)	Engine No:	20130019N63B44A
Reg. Date:	30/05/2012 (Man. Year: 2011)	Chassis No:	WBALX32050C952009
Colour:	Black	Odometer:	73793 km
Engine Capacity:	4395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,292.80	2,948.90	2,343.90	44.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,968.00	4,110.00	858.00	17.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>10,260.80</b>	<b>7,058.90</b>	<b>3,201.90</b>	<b>31.21</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	718.26	494.12	224.14	31.21
<b>Nett Amount (\$\$)</b>	<b>10,979.06</b>	<b>7,553.02</b>	<b>3,426.04</b>	<b>31.21</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (\$\$)</b>		500.00		
	<b>Nett Liability (\$\$)</b>	<b>8,053.02</b>		

### INSPECTION

Date of Assignment:	30/10/2020	
Date Inspected:	30/10/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

5/12/2021

Adjuster Report

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*SUNDRIES</b>	Necessary	150.00 FS	*80.00 FS
2	1		<b>*ALLOY RIM 9JX19 STY SPK 366</b>	Cut	1,490.05 FS	*1,231.40 FS
3	1		<b>*SLIDE ELEMEN</b>	Not Necessary	9.00 FS	*- FS
4	1		<b>*FRT LH FENDER</b>	Repair	1,120.75 FS	*- FS
5	1		<b>*SET OF MOUNT</b>	Not Necessary	33.55 FS	*- FS
6	1		<b>*FRT BUMPER CARRIER</b>	Not Necessary	783.75 FS	*- FS
7	1		<b>*FRT BUMPER IMPACT ABSORBER TOP</b>	Not Necessary	68.20 FS	*- FS
8	1		<b>*FRT BUMPER TRIM PRIMED (PDC)</b>	Deformed	1,565.90 FS	*1,565.90 FS
9	1		<b>*BMW EMBLEM</b>	Necessary	71.60 FS	*71.60 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>5,292.80</b>	<b>2,948.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER PANEL AND LEFT FRONT SIDE PANEL	New	2,125.00	1,700.00
2	TO RESPRAY FRONT BUMPER AND LEFT FRONT FENDER	New	1,923.00	1,730.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	450.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
6	TO CARRY OUT BODY CAVITYPRESERVATION (PER PANEL)	New	118.00	0.00
Gross Labour Cost (S\$)			<b>4,968.00</b>	<b>4,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >