

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011367/R1YF3E2

Date: 04/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900119581
Claimant Vehicle No : SMD5314L	Insured Vehicle No :	SMM7237R
Date of Loss: 19/10/2020	Nature of Claim: TP	Claim No: 9460924519SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD5314L	Engine No:	LEB5600956
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB71067646
Reg. Date:	24/08/2018 (Man. Year: 2018)	Odometer:	188657 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/10/2020	
Date Inspected:	20/10/2020 Inspected At:	Apex Motoring 25 Kaki Bukit Road 4, #01-55 Synergy @ KB Singapore 417800
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
4	1		*FRT BUMPER TOWING COVER	Deformed	0.00 F	*- F
5	1		*FRT BUMPER LOWER GRILLE	Deformed	0.00 F	*- F
6	1		*FRT GRILLE	Scratched	0.00 F	*- F
7	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
8	1		*REAR BUMPER	Deformed	0.00 F	*- F
9	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
10	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
11	1		*REAR END PANEL	Buckled	0.00 F	*- F
12	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
13	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
14	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
15	1		*TAILGATE	Buckled	0.00 F	*- F
16	1		*TAILGATE GARNISH	Cracked	0.00 F	*- F
17	1		*TAILGATE LOCK	Bent	0.00 F	*- F
18	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
19	1		*SPARE TYRE PANEL (FLOOR)	Repair	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >