

AUTOPROBE CONSULTANTS

To: AXA INSURANCE PTE LTD
C/O: SEAH ONG & PARTNERS LLP
36 ROBINSON ROAD
#12-03 CITY HOUSE
SINGAPORE 068877

Our Ref.: SVY200700002
Date: 01/07/2020

AUTOMOBILE INSPECTION REPORT

1. SURVEY TYPE: THIRD PARTY

Assignment Date:	30/06/2020	Your Reference:	20.27957 V
Vehicle Inspected:	GBA-4277-M	Policy Excess:	-
Insured Vehicle:	PC -8868-E		
Date of Accident:	15/10/2019	Surveyed / Assessed Date:	01/07/2020
Repairer / Survey at:	CHOO MOTOR SPRAY PAINTER		

2. VEHICLE PARTICULARS:

Make & Model:	OPEL COMBO-C 1.3DTJ MTA E4	General Condition:	FAIR
Registration Date:	02/07/2007	Colour:	SILVER
Engine Capacity:	1248	Odometer (km):	230902
Chassis No.:	W0L0XCF2574306606	Steering:	IN ORDER
Engine No.:	Z13DTJ1948932	Brake:	IN ORDER

3. TYRE CONDITION:

	Size	Make	Thread Depth (%)
FRONT LEFT	185/60R15	BRIDGESTONE	60
FRONT RIGHT	185/60R15	BRIDGESTONE	60
REAR LEFT	185/60R15	BRIDGESTONE	60
REAR RIGHT	185/60R15	BRIDGESTONE	60

4. DESCRIPTION OF DAMAGES:

The vehicle sustained damages mainly at the rear right portion.

AUTOPROBE CONSULTANTS

Your Ref.: 20.27957 V
Our Ref.: SVY200700002

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

5. ADJUSTMENT SUMMARY:

Original Estimate:	\$8,575.94
Revised:	\$5,998.03
Final Adjustment:	\$4,800.00 (Lump Sum)
Estimated Repair Duration:	4.00 Working Days

6. ESTIMATED VALUE (at time of accident):

Market/Book Value:	\$15,000.00 (COE Expiry: 01/07/2022)
LTA Rebate:	\$9,236.00 (as at 15/10/2019)
Nett:	\$5,764.00

7. INSPECTIONS

Pre-repair inspection conducted on 16/10/2019.
Dismantled parts inspection conducted on 18/10/2019.
Post-repair inspection conducted on 21/10/2019.

The Inspection was conducted on a "Without Prejudice" basis.

Assessor: TAY BH

AUTOPROBE CONSULTANTS

Your Ref.: 20.27957 V
Our Ref.: SVY200700002

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

ADJUSTMENT DETAILS

QTY	DESCRIPTION (PARTS)	CONDITION	ESTIMATE	REVISED
1	TAILGATE WIPER BLADE RH	SERVICEABLE	\$62.30 L	- L
1	TAILGATE WIPER ARM RH	BENT	\$79.80 L	\$79.80 L
1	TAILGATE WIPER MOTOR RH	DISTORTED	\$329.50 L	\$329.50 L
1	TAILGATE RUBBER LH	SERVICEABLE	\$269.00 L	- L
1	TAILGATE EMBLEM LH (OPEL)	NOT NECESSARY	\$82.50 L	- L
1	TAILGATE RH	DENTED	\$1,360.40 L	\$1,360.40 L
1	TAILGATE INNER BOARD RH	MTG CRACKED	\$768.20 L	\$520.00 L
1	TAILGATE EMBLEM RH (DTI)	NECESSARY	\$78.00 L	\$78.00 L
1	TAILGATE GLASS RH	CRACKED	\$428.00 L	\$428.00 L
1	TAILGATE RUBBER RH	DEFORMED	\$269.00 L	\$269.00 L
1	TAILGATE LOCK LOWER RH	DISTORTED	\$367.00 L	\$250.00 L
1	TAILGATE LOCK TOP RH	SERVICEABLE	\$248.50 L	- L
2	TAILGATE HINGE RH	LOWER DISTORTED	\$336.00 L	\$168.00 L
1	TAILGATE OUTER HANDLE RH	SERVICEABLE	\$168.00 L	- L
1	TAILGATE GARNISH RH	GRAZED	\$198.00 L	\$135.00 L
1	REAR BUMPER	DEFORMED	\$935.00 L	\$935.00 L
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	\$580.90 L	- L
1	REAR TAIL LAMP RH	CRACKED	\$234.00 L	\$234.00 L
1	REAR END PANEL TOP TRIM	SERVICEABLE	\$312.50 L	- L
1	TAILGATE INNER BOARD CLIPS	RH NECESSARY	\$40.00 S	\$20.00 S
2	TAILGATE STICKER (70KM/H & 5 PAX)	NECESSARY	\$20.00 S	\$20.00 S
1	REAR BUMPER SENSOR	DAMAGED	\$220.00 S	\$220.00 S
1	REAR GLASS SEALANT RH	NECESSARY	\$50.00 S	\$50.00 S
Subtotal			\$7,436.60	\$5,096.70
List Item Discount on L Items 10.00% / 10.00%			(\$710.66)	(\$478.67)
Total Parts			\$6,725.94	\$4,618.03

DESCRIPTION (LABOUR & MISC.)	ESTIMATE	REVISED
TO CHECK WIRING.	\$30.00	\$30.00
TUFF KOTE.	\$60.00	\$40.00
REMOVE & REFIX REAR WINDSCREEN.	\$120.00	\$120.00
REMOVE & REPLACE REVERSE SENSOR.	\$40.00	\$40.00

AUTOPROBE CONSULTANTS

Your Ref.: 20.27957 V
Our Ref.: SVY200700002

Vehicle No.: GBA-4277-M
Date of Accident: 15/10/2019

TO REMOVE & REPLACE SPARE PART & PANEL BEATING.	\$800.00	\$550.00
TO SPRAY PAINTING & ETC.	\$800.00	\$600.00
Subtotal	\$1,850.00	\$1,380.00
Total Labour	\$1,850.00	\$1,380.00
Total	\$8,575.94	\$5,998.03