

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20011369/UTF3E2

Date: 12/11/2020

REFERENCE

Insured/Claimant:	KOH POH LYE	Policy No:	Z19VP05025086	
Date of Loss:	17/10/2020	Nature of Claim:	OD	Claim No: 19/20/20/VP05/023787

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU2070G		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YB39278
Reg. Date:	27/11/2017 (Man. Year: 2017)	Chassis No:	JF1SJ5KC5JG100098
Colour:	Brown	Odometer:	31494 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,817.50	2,817.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,095.00	1,350.00	745.00	35.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,912.50	4,167.50	745.00	15.17
- Excess (\$\$)	0.00	500.00	-500.00	
(\$\$)	4,912.50	3,667.50	1,245.00	25.34
+ GST 7.00/7.00% (\$\$)	343.88	256.73	87.15	25.34
Nett Amount (\$\$)	5,256.38	3,924.23	1,332.15	25.34

INSPECTION

Date of Assignment:	20/10/2020 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	22/10/2020 Inspected At:	SME Motor Pte Ltd (Kaki Bukit)
		1 Kaki Bukit Ave 6 #02-15, AutoBay @
		Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU2070G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR (WCP)	Badly Dented	495.00 F	*495.00 F
2	1		*REAR RH DOOR STICKER (WCP)	Necessary	55.00 F	*55.00 F
3	1		*REAR RH DOOR LOWER PROTECTOR (WCP)	Grazed	120.00 F	*120.00 F
4	8		*PROTECTOR CLIP (WCP)	Necessary	16.00 F	*16.00 F
5	1		*FRT RH DOOR (WCP)	Badly Dented	495.00 F	*495.00 F
6	1		*FRT RH DOOR LOWER PROTECTOR (WCP)	Grazed	160.00 F	*160.00 F
7	8		*PROTECTOR CLIP (WCP)	Necessary	16.00 F	*16.00 F
8	1		*FRT FENDER RH (WCP)	Badly Dented	180.00 F	*180.00 F
9	1		*FRT FENDER INNER COWLING (WCP)	Distorted	95.00 F	*95.00 F
10	10		*INNER COWLING CLIP (WCP)	Necessary	20.00 F	*20.00 F
11	1		*FRT FENDER LOWER PROTECTOR RH (WCP)	Grazed	25.00 F	*25.00 F
12	4		*PROTECTOR CLIP (WCP)	Necessary	8.00 F	*8.00 F
13	1		*REAR RH SPORT RIM (ORI 17 INCH) (WCP)	Cut	650.00 F	*650.00 F
14	1		*REAR FENDER WHEEL ARC RUBBER SEAL RH (WCP)	Grazed	55.00 F	*55.00 F

Supplementary #1

15	1		*FRT RH DOOR STICKER (SET) (WCP)	Necessary	60.00 F	*60.00 F
----	---	--	--	-----------	---------	----------

F=Franchise part.

Sub Total (\$)	2,450.00	2,450.00
+ Margin on L,N Items 15.00/15.00% (\$)	367.50	367.50
Total Parts (\$)	2,817.50	2,817.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	20.00
2	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	150.00	120.00
3	REPLACE REAR RIM & BALANCING	New	50.00	0.00
4	WHEEL ALIGNMENT	New	65.00	60.00
5	LABOUR CHARGE	New	850.00	400.00
6	SPRAY PAINTING	New	950.00	750.00
Gross Labour Cost (S\$)			2,095.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >