



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                              |                                |   |  |
|--|------------------------------|--------------------------------|---|--|
| CHINA TAIPING INSURANCE (S) PTE LTD  |                              | Ref : CS3/CTI19015309/Qvf3s2-1 |   |  |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909  |                              | Date : 03-11-2020              |  |  |
|  |                              | Code : CTI                     |   |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |                              |                                |   |  |
| Insured Veh.   | PC 643P                      | Veh. Inspected                 | GBH 9808L   |  |
| Policy No.   | DMB1SN18258918000            | Coverage (\$)                  | 0.00  |  |
| Claim No.  | SNM19D204048C02              | Excess (\$)                    | 0.00  |  |
| Assign From  | JENNY LEW                    | Assign Date                    | 20/10/2020  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                              |                                |   |  |
| Make & Model   | TOYOTA HIACE                 | c.c                            | 2982  |  |
| Engine No.   | HIDDEN                       | Year of Reg.                   | 2018  |  |
| Chassis No.  | JTFHT02P800246144            | Colour                         | SILVER  |  |
| Odometer   | 16151                        | Steering                       | IN ORDER  |  |
| Brakes   | IN ORDER                     | Modification                   | NIL   |  |
| General  | GOOD                         |                                |   |  |
| <b>3. Conditions of Tyres</b>  |                              |                                |   |  |
|  | Size                         | Make                           | Balance   |  |
| R/H Front Tyre   | 195/ R15C                    | BRIDGESTONE                    | 6 mm  |  |
| L/H Front Tyre   | 195/ R15C                    | BRIDGESTONE                    | 6 mm  |  |
| R/H Rear Tyre  | 195/ R15C                    | BRIDGESTONE                    | 6 mm  |  |
| L/H Rear Tyre  | 195/ R15C                    | BRIDGESTONE                    | 6 mm  |  |
| <b>4. Description of Damages</b>   |                              |                                |   |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.   |                              |                                |   |  |
| <b>5. General Information</b>  |                              |                                |   |  |
| Accident Date  | 28/08/2019                   | Inspection Date                | 29/08/2019  |  |
| Survey held at   | M.LEASING-51 UBI AVE 1#03-18 |                                |   |  |
| Repairer   | -                            |                                |   |  |
| <b>5a. Remarks</b>   |                              |                                |   |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                              |                                |   |  |
| <b>5b. Estimate Days of Repair</b>   |                              |                                |   |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |                              | <b>8 Working Days</b>          |   |  |