

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20011373/DTF3Q2

**Date:** 01/12/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004922000

**Claimant Vehicle No :** SKP8110Z **Insured Vehicle No :** SGR1963L

Date of Loss: 18/10/2020 Nature of Claim: TP Claim No: SNM20D203927/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8110Z	Engine No:	L13B3932211
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GK33417720
Reg. Date:	10/02/2020 (Man. Year: 2019)	Odometer:	13610 km
Colour:	Blue		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,598.48	0.00	2,598.48	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	200.00	2,050.00	91.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,848.48</b>	<b>200.00</b>	<b>4,648.48</b>	<b>95.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>339.39</b>	<b>14.00</b>	<b>325.39</b>	<b>95.87</b>
<b>Nett Amount (S\$)</b>	<b>5,187.87</b>	<b>214.00</b>	<b>4,973.87</b>	<b>95.87</b>

### INSPECTION

Date of Assignment: 21/10/2020

Date Inspected: 20/11/2020 Inspected At:

JWG International Pte Ltd (HQ)  
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08  
AMK AutoPoint  
Singapore 568047

Estimated Period of Repair: 2.0 days

**Adjuster:** BRYAN TANI

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
<b>Parts:</b>	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKP8110Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	683.20 FL	*- FL
2	1		*REAR BUMPER SIDE GARNISH RH	Not Necessary	174.90 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	48.20 FL	*- FL
4	1		*REAR END PANEL	Not Necessary	692.30 FL	*- FL
5	1		*REAR FENDER RH	Not Necessary	1,012.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
7	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
8	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
9	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,120.60</b>	<b>0.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	522.12	0.00
<b>Total Parts (\$\$)</b>	<b>2,598.48</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	800.00	0.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	800.00	200.00
3	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	0.00
4	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
5	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,250.00</b>	<b>200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >