

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20011381/KBA3Q2

**Date:** 07/12/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMM9861A	<b>Insured Vehicle No :</b>	SHA2044K
Date of Loss: 02/10/2020	Nature of Claim: TP	Claim No: MCT20100020

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM9861A</b>		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B3931795
Reg. Date:	22/07/2019 (Man. Year: 2019)	Chassis No:	GK33417304
Colour:	Metallic Red	Odometer:	15348 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/75 R14	Rear Tyre Size:	175/75 R14
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,928.32	1,296.80	631.52	32.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	570.00	490.00	46.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,988.32</b>	<b>1,866.80</b>	<b>1,121.52</b>	<b>37.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	209.18	130.68	78.50	37.53
<b>Nett Amount (S\$)</b>	<b>3,197.50</b>	<b>1,997.48</b>	<b>1,200.02</b>	<b>37.53</b>
<b>+ Loss of Use (3.0 x S\$70.00/day) (S\$)</b>		210.00		
		<b>2,207.48</b>		
		<b>2,200.00</b>		

### INSPECTION

Date of Assignment:	19/10/2020	
Date Inspected:	19/10/2020 Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2020)
<b>Parts:</b>	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM9861A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,080.50 FL	*845.20 FL
2	1		*FRONT RH DOOR FRAME STICKER 1	Necessary	95.00 FL	*60.00 FL
3	1		*FRONT RH DOOR FRAME STICKER 2	Necessary	90.00 FL	*90.00 FL
4	1		*FRONT RH DOOR MOULDING	Dented	225.50 FL	*86.60 FL
5	1		*FRONT RH DOOR HANDLE	Distorted	285.20 FL	*285.20 FL
6	1		*FRONT RH DOOR HANDLE FRONT RUBBER	Dented	58.50 FL	*58.50 FL
7	1		*FRONT RH DOOR HANDLE BASE	Dented	195.50 FL	*195.50 FL
8	1		*FRONT RH DOOR GLASS GEAR & MOTOR	Serviceable	380.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,410.40</b>	<b>1,621.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	482.08	324.20
<b>Total Parts (\$\$)</b>	<b>1,928.32</b>	<b>1,296.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT FRONT RH DOOR GLASS	New	100.00	60.00
2	WIRING	New	80.00	20.00
3	TUFFKOTE	New	80.00	30.00
4	SPRAY PAINTING	New	400.00	260.00
5	LABOUR CHARGES	New	400.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>1,060.00</b>	<b>570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >