

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20011390/ETD3E2

Date: 24/12/2020

REFERENCE

Insured/Claimant: TAN AMAS Policy No: DMCVSNW00016542002

Date of Loss: 10/10/2020 Nature of Claim: OD Claim No: SNM20D203812/C01/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGP8511Y**
Make & Model: JAGUAR E-PACE, 2.0 S (A) Engine No: 160524W0305204DTD
Reg. Date: 08/08/2016 (Man. Year: 2016) Chassis No: SADCA2AN6HA067762
Colour: Silver Odometer: 64457 km
Engine Capacity: 1999 cc
Market Value/New Car Price: S\$128,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,603.40	12,199.00	17,404.40	58.79
Miscellaneous Items	500.00	0.00	500.00	100.00
Labour	2,811.99	3,373.15	-561.16	-19.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,915.39	15,572.15	17,343.24	52.69
+ GST 7.00/7.00% (S\$)	2,304.08	1,090.05	1,214.03	52.69
Nett Amount (S\$)	35,219.47	16,662.20	18,557.27	52.69

INSPECTION

Date of Assignment: 20/10/2020

Date Inspected: 21/10/2020 Inspected At:

53 UBI AVENUE 1 # 01-24
Repairer : Goldbell Engineering Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2020)
Parts:	M1-SUV	JAGUAR E-PACE 2.0 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP8511Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	966.00 F	*- F
2	1		*FRONT BUMPER RETAINER	Not Necessary	50.40 F	*- F
3	1		*FRONT DAYLIGHT LH	Not Necessary	336.00 F	*- F
4	1		*FRONT LH FENDER	Dented	636.00 F	*636.00 F
5	1		*FRONT LH FENDER INNER SHIELD	Crushed	36.00 F	*318.00 F
6	1		*FRONT BONNET	Not Necessary	1,506.00 F	*- F
7	1		*FRONT BONNET HINGE	Not Necessary	172.80 F	*- F
8	1		*FRONT LH DOOR PANEL	Dented	1,200.00 F	*1,200.00 F
9	1		*FRONT LH DOOR INNER TRIM	Not Necessary	1,668.00 F	*- F
10	1		*FRONT LH DOOR REGULATOR MOTOR	Not Necessary	240.00 F	*- F
11	1		*FRONT LH DOOR LOCK ASSY	Jammed	252.00 F	*252.00 F
12	1		*FRONT LH DOOR WEATHERSTRIP	Necessary	84.00 F	*84.00 F
13	1		*FRONT LH DOOR HINGE UPPER	Bent	72.00 F	*72.00 F
14	1		*FRONT LH DOOR HINGE LOWER	Bent	72.00 F	*72.00 F
15	1		*FRONT LH DOOR CHECKER	Not Necessary	60.00 F	*- F
16	1		*FRONT LH DOOR CHROME MOUDLING UPPER	Not Necessary	144.00 F	*- F
17	1		*FRONT LH DOOR CHROME MOULDING LOWER	Not Necessary	126.00 F	*- F
18	1		*FRONT LH DOOR GARNISH	Not Necessary	98.40 F	*- F
19	1		*REAR LH DOOR GARNISH	Not Necessary	108.00 F	*- F
20	1		*REAR LH DOOR PANEL	Repair	1,452.00 F	*- F
21	1		*REAR LH DOOR CHROME MOULDING UPPER	Not Necessary	120.00 F	*- F
22	1		*REAR LH DOOR CHROME MOULDING LOWER	Not Necessary	126.00 F	*- F
23	1		*REAR LH DOOR HANDLE	Repair	264.00 F	*- F
24	1		*FRONT LH WING MIRROR HOUSING	Broken	660.00 F	*660.00 F
25	1		*FRONT LH WING MIRROR GLASS	Not Necessary	408.00 F	*- F
26	1		*FRONT LH WING MIRROR MOTOR	Not Necessary	134.40 F	*- F
27	1		*FRONT LH WING MIRROR COVER	Not Necessary	92.40 F	*- F
28	1		*STEERING RACK	Broken	5,286.00 F	*5,286.00 F
29	1		*FRONT LH KNUCKLE ARM	Not Necessary	1,488.00 F	*- F
30	1		*FRONT LH KNUCKLE ARM BEARING	Not Necessary	477.60 F	*- F
31	1		*FRONT LH LOWER ARM	Bent	462.00 F	*462.00 F
32	1		*FRONT LH UPPER ARM	Bent	438.00 F	*438.00 F
33	1		*FRONT LH SHOCK ABSORBER	Not Necessary	282.00 F	*- F
34	1		*FRONT LH CONTROL ARM	Bent	424.80 F	*424.80 F
35	1		*FRONT LH ABS SENSOR	Not Necessary	211.20 F	*- F
36	1		*FRONT LH BRAKE CALIPER	Not Necessary	264.00 F	*- F
37	1		*FRONT CROSSMEMBER	Not Necessary	3,240.00 F	*- F
38	1		*FRONT LH SIDE SKIRT	Not Necessary	1,560.00 F	*- F
39	1		*FRONT LH MOULDING	Cut	50.40 F	*50.40 F
40	1		*FRONT CENTRE MOULDING	Cut	255.60 F	*255.60 F
41	1		*FRONT LH HEADLAMP	Not Necessary	1,800.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT LH PILLAR A (NPA)	Repair	0.00 F	*- F
43	1		*RIM (NPA)	Not Necessary	0.00 F	*- F
44	1		*TYRE (NPA)	Not Necessary	0.00 F	*- F
45	1		*POWER STEERING OIL	Necessary	-	*100.00 F
<u>Supplementary #1</u>						
46	1		*THERMOSTAT HOUSING	Cracked	153.60 F	*153.60 F
47	1		*TIE ROD	Not Necessary	248.40 F	*- F
48	1		*TIE ROD END	Not Necessary	142.80 F	*- F
49	1		*FENDER OUTER GARNISH	Broken	231.60 F	*231.60 F
<u>Supplementary #2</u>						
50	1		*L/F PRESSURE VALVE	Necessary	15.00 F	*15.00 F
51	1		*L/F WHEEL	Cut	1,488.00 F	*1,488.00 F
F=Franchise part.						
Total Parts (\$\$)					29,603.40	12,199.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BRAKE FULID (NOT NECESSARY)	60.00	0.00
2	1	FRONT BUMPER CLIP (SET) (NOT NECESSARY)	40.00	0.00
3	1	FRONT DOOR INNER TRIM CLIP (SET) (NOT NECESSARY)	50.00	0.00
4	1	FRONT DOOR INNER TRIM CLIP (SET) (NOT NECESSARY)	50.00	0.00
5	1	FRONT FENDER INNER SHIELD CLIP (SET) (NOT NECESSARY)	50.00	0.00
6	1	FRONT LH CENTRE MOULDING CLIP (SET) (NOT NECESSARY)	50.00	0.00
7	1	FRONT LH MOULDING CLIP (SET) (NOT NECESSARY)	50.00	0.00
8	1	LH SIDE SKIRT CLIP (SET) (NOT NECESSARY)	50.00	0.00
9	1	POWER STEERING OIL (NOT NECESSARY)	100.00	0.00
Sub Total (\$\$)			500.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RATE 20.0 WU X 42.00 SGD / H	New	-	84.00
Supplementary #2				
Labour Items				
2	TOTAL OF LABOUR	New	1,507.80	1,869.00
3	TOTAL OF PAINT INCLUDING OF MATERIAL	New	1,304.19	1,420.15
Gross Labour Cost (\$\$)			2,811.99	3,373.15

Report was unsubmitted during this print-out.

< END OF ESTIMATES >