



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007896
INV Date 24/11/2020
Reference CC3/LPC20011396/Kps3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 660D
Insured Veh. YP 9617G
Claim No. 20/20/20/VC00/023785
Policy No. Z/20/VC00/108763
Accident Date 15/10/2020
Inspection Date 19/10/2020

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC20011396/Kps3q2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-11-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------------|----------------|------------|
| Insured Veh. | YP 9617G | Veh. Inspected | SHD 660D |
| Policy No. | Z/20/VC00/108763 | Coverage (\$) | 0.00 |
| Claim No. | 20/20/20/VC00/023785 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 19/10/2020 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|---------------------|
| Make & Model | RENAULT LATITUDE | c.c | 1995 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | VF1ABL15AUC283410 | Colour | METALLIC WHITE /RED |
| Odometer | 433774 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 215/60 R16 | SAILUN | 9 mm |
| L/H Front Tyre | 215/60 R16 | SAILUN | 9 mm |
| R/H Rear Tyre | 215/60 R16 | SAILUN | 9 mm |
| L/H Rear Tyre | 215/60 R16 | SAILUN | 9 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 15/10/2020 | Inspection Date | 19/10/2020 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 660D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | BUMPER COVER FRT | CRACKED | 747.20 | 747.20 |
| 1 | BUMPER BEAM FRT | TO REPAIR SEE LABOUR | 663.70 | - |
| 1 | BUMPER SPOILER FRT | DISTORTED | 344.70 | 344.70 |
| 1 | BUMPER ABSORBER FRT | CRACKED | 394.68 | 394.68 |
| 1 | BUMPER BRACKET FRT RH (HEADLAMP LOWER) | CRACKED | 116.47 | 116.47 |
| 1 | BUMPER ETAINER FRT RH | CRACKED | 101.40 | 101.40 |
| 1 | BUMPER SUPPORT FRT | SERVICEABLE | 10.70 | - |
| 1 | RADIATOR GRILLE | MTG CRACKED | 969.90 | 969.90 |
| 1 | RADIATOR GRILLE FRAME | CRACKED | 686.00 | 686.00 |
| 1 | RADIATOR GRILLE BADGE 'RENAULT' | NECESSARY | 225.36 | 225.36 |
| 1 | BUMPER GRILLE LOWER FRT | SERVICEABLE | 147.00 | - |
| 1 | BUMPER FOG LAMP GRILLE RH | MISSING | 207.21 | 207.21 |
| 1 | HEADLAMP RH | MTG CRACKED | 743.60 | 743.60 |
| 1 | HEADLAMP PANEL FRT RH | TO REPAIR SEE LABOUR | 128.30 | - |
| 1 | FENDER PANEL FRT RH | TO REPAIR SEE LABOUR | 437.10 | - |
| 1 | BUMPER UNDERTRAY FRT | SERVICEABLE | 292.50 | - |
| 1 | SUBFRAME OUTER FRT | SERVICEABLE | 1,094.20 | - |
| 1 | WHEELARCH FRT RH | CRACKED | 191.40 | 191.40 |
| | LESS 10% DISCOUNT | | -750.14 | -472.79 |
| | | | 6,751.28 | 4,255.13 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET BUMPER CLIP FRT (SN) | NECESSARY | 90.00 | 66.00 |
| 1 | BUMPER BRACKET CLIP FRT (SN) | NOT NECESSARY | 75.00 | - |
| 1 | BUMPER SUPPORT CLIP FRT (SN) | NOT NECESSARY | 10.00 | - |
| 1 | SET BUMPER RETAINER CLIP FRT (SN) | NOT NECESSARY | 70.00 | - |
| 1 | SET BUMPER GRILLE LOWER CLIP (SN) | NOT NECESSARY | 70.00 | - |
| 1 | BUMPER FOG LAMP GRILLE CLIP (SN) | NOT NECESSARY | 65.00 | - |
| 1 | BUMPER SPOILER CLIP (SN) | NOT NECESSARY | 60.00 | - |

Report Ref No. CC3/LPC20011396/Kps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|---|--|---------------|----------------------------|-------------------|
| 1 | SET WHEELARCH CLIP FRT (SN) | NECESSARY | 80.00 | 80.00 |
| 1 | SET RADIATOR GRILLE SCREW (SN) | NOT NECESSARY | 60.00 | - |
| 1 | SET RADIATOR GRILLE FRAME CLIP L70Y (SN) | NECESSARY | 65.00 | 65.00 |
| 1 | TOWING FEE (SN) | NOT NECESSARY | 170.00 | - |
| | | | 815.00 | 211.00 |
| | LABOUR | | | |
| | TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. | NOT NECESSARY | 380.00 | - |
| | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT ,HEADLAMP PANEL FRT RH AND FENDER PANEL FRT RH . | | 1,800.00 | 500.00 |
| | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR. | NOT NECESSARY | 380.00 | - |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | | 170.00 | 20.00 |
| | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS. | NOT NECESSARY | 250.00 | - |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | - |
| | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING. | NOT NECESSARY | 170.00 | - |
| | TO REMOVE AND REFIT BATTERY ,ELECTRICAL WIRING ,FUSE BOX AND RELAY TO ENABLE REPAIR. | NOT NECESSARY | 450.00 | - |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION . | | 1,800.00 | 440.00 |
| | | | 5,620.00 | 960.00 |
| GRAND TOTAL | | | 13,186.28 | 5,426.13 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,350.00 |

Report Ref No. CC3/LPC20011396/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 660D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 660D

RE-INSPECTION

