

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG20011397/R1GS3Q2

Date:

11/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100285496

Claimant Vehicle No : SJJ6304M**Insured Vehicle No :**

SX3004T

Date of Loss: 18/09/2020

Nature of Claim:

TP

Claim No:

3479192536SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJJ6304M**

Make & Model: TOYOTA CAMRY, 2.4 ABS AIRBAG (A)

Engine No: 2AZE108002

Reg. Date: 22/09/2008 (Man. Year: 2008)

Chassis No: MR053BK4007028865

Colour: Gold

Odometer: 229168 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,243.25	1,380.75	862.50	38.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,040.00	890.00	46.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,173.25	2,420.75	1,752.50	41.99
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/10/2020

Date Inspected: 29/10/2020 Inspected At: Sin Hup Lee Service Co (HQ)
Blk 1005 Bukit Merah Lane 2, #01-209 Alexandra Village Industrial Estate
Singapore 159761

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	465.00 FL	*465.00 FL
2	1		*FRONT HEAD LAMP LH	Scratched	718.00 FL	*718.00 FL
3	1		*FRONT FENDER LH	Buckled	310.00 FL	*310.00 FL
4	1		*FRONT FENDER COWLING	Cut	118.00 FL	*118.00 FL
5	1		*FRONT DOOR LH	Repair	568.00 FL	*- FL
6	1		*FRONT DOOR MOULDING	Serviceable	55.00 FL	*- FL
7	1		*FRONT DOOR PROTECTOR	Serviceable	38.00 FL	*- FL
8	1		*SIDE SKIRT	Repair	489.00 FL	*- FL
9	1		*TYRE RIM	Scratched	180.00 FL	*180.00 FL
10	1		*FRONT SIDE BRACKET	Cut	50.00 FL	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,991.00	1,841.00
- List Item Discount on L Items 25.00/25.00% (S\$)	747.75	460.25
Total Parts (S\$)	2,243.25	1,380.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPIAR ,REMOVE & REFIX DAMAGED PARTS ,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	850.00	400.00
2	TO SPRAY PAINT WORK ON AFFECTED AREAS	New	780.00	600.00
3	TO REMOVE AND REFIX DOOR GLASS MECHANISM ,CHECK AND TEST MOTOR AND CENTRE LOCKING SYSTEM	New	200.00	0.00
4	TO RUST PROOF AFFECTED AREAS	New	100.00	40.00
Gross Labour Cost (\$\$)			1,930.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >