

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011409/T1VF3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30978419022
Claimant Vehicle No :	SLV3948M	Insured Vehicle No :	SLV7779H
Date of Loss:	16/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203899C02/KAHLEONG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3948M	Engine No:	2ZRS088720
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	ZVW506092149
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	214370 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,684.20	9,162.90	5,521.30	37.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,990.00	7,597.00	1,393.00	15.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	23,674.20	16,759.90	6,914.30	29.21

INSPECTION

Date of Assignment:	21/10/2020	
Date Inspected:	21/10/2020 Inspected At:	Inchcape Centre (HQ) 2 PANDAN CRESCENT, LEVEL 4 BODYCARE CENTRE Singapore 128462
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2020)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3948M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	10		*PIECE RR BUMPER	Necessary	41.00 FS	*41.00 FS
3	1		*GUARD ,RR BUMPER	Deformed	576.30 FS	*576.30 FS
4	1		*PANEL SUB-ASSY ,BODY	Bent	650.30 FS	*650.30 FS
5	1		*COVER ,DECK TRIM ,RR	Deformed	168.50 FS	*168.50 FS
6	1		*BOARD ,RR FLOOR	Deformed	526.10 FS	*526.10 FS
7	1		*LOCK ASSY ,BACK DOOR	Bent	467.00 FS	*467.00 FS
8	1		*PLATE ,LUGGAGE	Necessary	47.90 FS	*47.90 FS
9	1		*PLATE ,LUGGAGE COMPT	Necessary	57.40 FS	*57.40 FS
10	1		*PLATE ,LUGGAGE COMPT	Necessary	54.60 FS	*54.60 FS
11	1		*GARNISH SUB-ASSY	Cracked	925.60 FS	*925.60 FS
12	1		*SPOILER SUB-ASSY ,RR	Not Necessary	2,687.80 FS	*- FS
13	1		*LENS & BODY ,RR	Not Necessary	451.80 FS	*- FS
14	1		*LENS & BODY ,RR	Cracked	443.30 FS	*443.30 FS
15	1		*DAM ,WINDOW GLASS	Necessary	28.90 FS	*28.90 FS
16	1		*GLASS SUB-ASSY ,BACK	Necessary	1,449.60 FS	*1,449.60 FS
17	1		*GLASS SUB-ASSY ,BACK	Necessary	761.40 FS	*761.40 FS
18	1		*WEATHERSTRIP ,BACK	Cut	372.30 FS	*372.30 FS
19	1		*PANEL SUB-ASSY ,FR	Not Necessary	1,881.30 FS	*- FS
20	2		*SIKA 182010 SIKA TACK GO!(BLA)	Necessary	216.00 FS	*216.00 FS
21	2		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	400.00 FS	*400.00 FS
22	1		*PANEL SUB-ASSY ,BACK	Bent	1,147.80 FS	*1,147.80 FS
23	1		*COVER ,RR BUMPER	Deformed	442.60 FS	*442.60 FS
24	1		*COVER ,BACK DOOR	Deformed	30.20 FS	*30.20 FS
25	1		*BACK SENSOR ATTITUDE BLACK MC	Not Working	169.60 FS	*169.60 FS
26	1		*REINFORCEMENT	Not Necessary	332.70 FS	*- FS
27	1		*RETAINER ,RR BUMPER	Necessary	116.50 FS	*116.50 FS
28	1		*RETAINER ,RR BUMPER	Not Necessary	117.70 FS	*- FS
29	1		*PHV STICKER	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **14,684.20** **9,162.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND CONDUCT LEAK TEST	New	180.00	180.00
2	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
3	TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA	New	540.00	540.00
4	R/I INTERIOR TRIMMING TO FAC REPAIR	New	360.00	360.00
5	REPL REAR WINDSCREEN AND BOOT WINDOW	New	800.00	717.00
6	RTEPL ACC AFF PARTS ANDPANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	3,600.00	2,880.00
7	RESPRAY ACC AFF AREA	New	2,950.00	2,360.00
8	SUPPLY SEPAANT (NETT) 2 PANEL	New	200.00	200.00
9	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	180.00
Gross Labour Cost (\$\$)			8,990.00	7,597.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >