

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011410/AGA3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLQ1852U	Insured Vehicle No :	SHC3443A
Date of Loss:	18/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100296

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1852U		
Make & Model:	SSANGYONG TIVOLI XLV, 1.6 G 6AT 2WD ESP E4 (A)	Engine No:	17391002055928
Reg. Date:	29/06/2017 (Man. Year: 2016)	Chassis No:	KPT36B1VSGP107615
Colour:	Black	Odometer:	100908 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,046.27	1,984.98	5,061.29	71.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,955.00	710.00	2,245.00	75.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,001.27	2,694.98	7,306.29	73.05
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	10,001.27	2,100.00	7,901.27	79.00
+ GST 7.00/7.00% (S\$)	700.09	147.00	553.09	79.00
Nett Amount (S\$)	10,701.36	2,247.00	8,454.36	79.00
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,789.45		

INSPECTION

Date of Assignment:	21/10/2020	
Date Inspected:	21/10/2020 Inspected At:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2021)**Parts:** M1-SUV SSANGYONG TIVOLI XLV 1.6 G 6AT 2WD ESP E4 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLQ1852U)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PROTECTOR LH (STICK ON)	Cut	287.50 FL	*287.50 FL
2	1		*ROCKER SIDE SKIRTING LH	Cut	498.90 FL	*498.90 FL
3	1		*REAR DOOR LH	Repair	3,666.80 FL	*- FL
4	1		*REAR DOOR PROTECTOR LH (SKICK ON)	Cut	297.10 FL	*297.10 FL
5	1		*REAR FENDER ARCH GARNISH LH	Cut	288.70 FL	*288.70 FL
6	1		*REAR FENDER INNER SHIELD LH	Not Necessary	342.60 FL	*- FL
7	1		*REAR SUSPENSION WHEEL HUB BEARING LH	Not Necessary	458.40 FL	*- FL
8	1		*REAR 16 SPORT RIM LH	Cut	1,440.27 FS	*600.00 FS
9	1		*ROCKER SIDE SKIRTING CLIPS SET LH	Necessary	80.00 FS	*30.00 FS
10	1		*REAR FENDER ARCH GARNISH CLIPS SET LH	Necessary	60.00 FS	*20.00 FS
11	1		*REAR FENDER INNER SHIELD CLIPS SET LH	Not Necessary	60.00 FS	*- FS
12	1		*REAR FENDER ARCH GARNISH PROTECTOR (CARBON TYPE)	Cut	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,630.27	2,122.20
- List Item Discount on L Items 10.00/10.00% (\$)	584.00	137.22
Total Parts (\$)	7,046.27	1,984.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	800.00	300.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	800.00	300.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	105.00	30.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	0.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOT WITH DISTANCE SETTING	New	80.00	0.00
6	TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING	New	280.00	0.00
7	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH TO PERFORM FACILITATE REPAIRS	New	350.00	0.00
8	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	80.00
9	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
10	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (S\$)			2,955.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >