



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 5778D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP-LH	SCRATCHED	1,198.00	1,198.00
1	FRONT FENDER-LH	TO REPAIR SEE LABOUR	966.80	-
1	FRONT BUMPER	CUT / TORN	594.00	542.30
1	FRONT BUMPER SIDE RETAINER-LH	BENT	34.00	34.00
1	FRONT BUMPER FOG LAMP-LH	CRACKED	265.00	265.00
1	FRONT BUMPER FOG LAMP COVER-LH	SERVICEABLE	149.00	-
1	FRONT BUMPER AIRDUCT-LH	SERVICEABLE	64.00	-
	LESS 20% DISCOUNT		-654.16	-407.86
			2,616.64	1,631.44
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER-LH.		650.00	300.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.	NOT NECESSARY	60.00	-
	SPRAY PAINTING.		620.00	400.00
			1,390.00	720.00
	GRAND TOTAL		4,006.64	2,351.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS/AGI20011413/Uvf3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.