

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20011414/GQF3N2**Date:** 09/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00017542004		
<b>Claimant Vehicle No :</b>	SMM827J	<b>Insured Vehicle No :</b>	YP780B		
Date of Loss:	17/10/2020	Nature of Claim:	TP	Claim No:	SNM20D203945/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMM827J</b>		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B3884933
Reg. Date:	17/06/2019 (Man. Year: 2019)	Chassis No:	GK33415390
Colour:	Blue	Odometer:	14102 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,811.59	1,489.26	2,322.33	60.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,030.00	1,180.00	53.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,021.59</b>	<b>2,519.26</b>	<b>3,502.33</b>	<b>58.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	6,021.59	2,000.00	4,021.59	66.79
<b>+ GST 7.00/7.00% (S\$)</b>	421.51	140.00	281.51	66.79
<b>Nett Amount (S\$)</b>	<b>6,443.10</b>	<b>2,140.00</b>	<b>4,303.10</b>	<b>66.79</b>

**INSPECTION**

Date of Assignment:	21/10/2020		
Date Inspected:	21/10/2020	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days		

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2022)
<b>Parts:</b>	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM827J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	987.65 FL	*551.50 FL
2	1		*BONNET LOCK	Not Necessary	157.89 FL	*- FL
3	1		*BONNET INSULATOR (NPA)	Not Necessary	0.00 FL	*- FL
4	4		*BONNET OUTER RUBBER	Not Necessary	141.80 FL	*- FL
5	1		*FRONT BUMPER	Broken	744.86 FL	*517.70 FL
6	1		*FRONT BUMPER RETAINER (RH)	Not Necessary	36.47 FL	*- FL
7	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	41.52 FL	*- FL
8	1		*FRONT BUMPER FOG LIGHT GARNISH (RH)	Not Necessary	51.23 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	385.24 FL	*- FL
10	1		*FRONT BUMPER RADIATOR GRILLE CHROME	Not Necessary	541.23 FL	*- FL
11	1		*HEADLIGHT (RH)	Cracked	754.88 FL	*754.88 FL
12	1		*FRONT FENDER (RH)	Repair	665.47 FL	*- FL
13	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
14	1		*SET HEADLIGHT CLIP	Not Necessary	30.00 FS	*- FS
15	1		*FRONT NO PLATE	Not Necessary	50.00 FS	*- FS
16	1		*FRONT WINDSCREEN SEALANT	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,713.24</b>	<b>1,854.08</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	901.65	364.82
<b>Total Parts (\$\$)</b>	<b>3,811.59</b>	<b>1,489.26</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS,INCLUSIVE OF REPLACEMENT PARTS	New	800.00	400.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	1,000.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	0.00
4	TO SUPPLY UNDER COATING/PUTTY ON PARTS REPLACED	New	50.00	0.00
5	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	80.00	0.00
6	TO CHECK WIRING AND LIGHTING SYSTEM	New	80.00	30.00
7	REMOVE AND REFIT FRONT WINDSCREEN	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,210.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >