



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

INV No. AC2101747

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 18/03/2021

Reference CC6/QBE20011416/Urs3q2

Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SLS 1577D

Insured Veh. GX 7716M

Claim No. VC014056

Policy No. 8-V0013808-MVA-R003

Accident Date 19/10/2020

Inspection Date 21/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC6/QBE20011416/Urs3q2	
			Date: 18/03/2021	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 7716M	Veh. Inspected	SLS 1577D	
Policy No.	8-V0013808-MVA-R003	Coverage (\$)	0.00	
Claim No.	VC014056	Excess (\$)	0.00	
Assign From		Assign Date	21/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WDD2040452A276810	Colour	WHITE	
Odometer	191401 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/10/2020	Inspection Date	21/10/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1577D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEEP CUT	1,688.20	1,451.22
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	713.50	-
2	FRONT BUMPER CHROME MOULDINGS @\$165.00	NECESSARY	330.00	322.00
1	SET FRONT BUMPER RIVET	NECESSARY	50.00	50.00
1	HEADLAMP O/S	NOT NECESSARY	1,860.25	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	971.35	-
1	FRONT FENDER EMBLEM O/S	NECESSARY	98.20	98.20
1	FRONT FENDER CHROME MOULDING O/S	NECESSARY	99.50	80.50
1	FRONT SHOCK ABSORBER O/S	BENT	866.20	645.25
1	FRONT KNUCKLE ARM O/S	BENT	1,045.50	755.30
1	FRONT KNUCKLE ARM BEARING O/S	DAMAGED	485.00	455.00
1	FRONT TORSION ARM O/S	BENT	699.20	355.20
1	FRONT DOOR O/S	DENTED / WARPED	2,201.30	2,005.00
1	FRONT DOOR CHROME MOULDING O/S	NECESSARY	266.50	245.50
1	FRONT DOOR VIEW MIRROR COVER O/S	CRACKED	285.00	285.00
1	FRONT DOOR VIEW MIRROR ASSY O/S	CRACKED / DAMAGED	1,850.20	1,201.42
1	FRONT DOOR VIEW MIRROR LAMP O/S	NOT NECESSARY	235.00	-
1	FRONT DOOR GLASS OUTER CHROME MOULDING O/S	DENTED / NECESSARY	366.20	345.01
1	FRONT DOOR OUTER HANDLE O/S	TO REPAIR SEE LABOUR	385.00	-
1	FRONT DOOR FRAME GARNISH O/S	NECESSARY	120.00	120.00
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	399.00	330.00
2	FRONT DOOR HINGES @\$210.00	NOT NECESSARY	420.00	-
1	REAR DOOR O/S	TO REPAIR SEE LABOUR	2,005.20	-
1	REAR DOOR OUTER CHROME MOULDING O/S	NECESSARY	250.50	225.00
1	REAR DOOR INNER RUBBER O/S	NOT NECESSARY	395.00	-
1	ROCKER PANEL GARNISH O/S	DEFORMED / TORN	855.20	665.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	2,650.00	-

Report Ref No. CC6/QBE20011416/Urs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SPORT RIM O/S LESS 10% DISCOUNT	BENT	1,200.00 -	800.00 -1,043.46
			22,791.00	9,391.14
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.		180.00	150.00
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM.		100.00	80.00
	TO RESET & REPROGRAMME SYSTEM.		100.00	50.00
	TO SPRAY RUST PROOFING.		100.00	30.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S,FRONT DOOR OUTER HANDLE O/S,REAR DOOR O/S AND REAR FENDER O/S.		1,200.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,680.00	1,200.00
			3,710.00	2,110.00
GRAND TOTAL			26,501.00	11,501.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,200.00

Report Ref No. CC6/QBE20011416/Urs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 1577D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 1577D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 1577D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

