

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 97C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	692.80	559.10
2	REAR BUMPER SIDE RETAINER @\$56.80	N/S BENT	113.60	56.80
1	BUMPER REINFORCEMENT	DENTED	399.50	399.50
1	BUMPER REFLECTOR N/S	CRACKED	63.70	63.70
1	BOOT LID	TO REPAIR SEE LABOUR	1,086.30	-
1	BOOT LID INNER LOCK	SERVICEABLE	398.90	-
1	BOOT LID W/STRIP	TWISTED	198.70	198.70
1	TAIL LAMP N/S	CRACKED	573.00	573.00
1	REAR END PANEL	BADLY DENTED	696.30	696.30
1	REAR END PANEL INNER GARNISH	TWISTED	403.70	403.70
1	REAR FLOOR PANEL TOP BOARD	TORN	366.50	366.50
	LESS 20% DISCOUNT		-998.60	-
	LESS 25% DISCOUNT		-	-829.33
			3,994.40	2,487.97
	SPECIAL NETT ITEMS			
1	SET REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
10	REAR BUMPER CLIPS @\$5.00 (SN)	NECESSARY	50.00	40.00
			250.00	240.00
	<u>LABOUR</u>			
	TO REMOVE, REPLACED REVERSE SENSOR & CHECK WIRING.		80.00	50.00
	TO SPRAY PAINTING.		980.00	900.00
	TO REMOVE, REPLACE REAR BUMPER, BOOT LID & END PANEL. LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID.		920.00	840.00
			1,980.00	1,790.00
	GRAND TOTAL		6,224.40	4,517.97

RECOMMENDED COST OF LUMP SUM REPAIRS	3,600.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI20011417/Uyf3e2





Report Ref No. CS/AGI20011417/Uyf3e2

CHUA KANG SENG
Licensed Appraiser