

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20011419/DVF3Q2

Date: 04/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001412228

Claimant
Vehicle No : SHA3699P

Insured Vehicle No : YM3604Z

Date of Loss: 20/10/2020

Nature of Claim: TP

Claim No: 248840

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA3699P**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU409931

Reg. Date: 23/01/2020 (Man. Year: 2019)

Chassis No: KMHC851CVLU190275

Colour: Blue

Odometer: 0 km

Engine Capacity: 1580 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,605.92	12,858.52	7,747.40	37.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	2,240.00	2,600.00	53.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	25,445.92	15,098.52	10,347.40	40.66
+ GST 7.00/7.00% (\$\$)	1,781.21	1,056.90	724.31	40.66
Nett Amount (\$\$)	27,227.13	16,155.42	11,071.71	40.66

INSPECTION

Date of Assignment: 21/10/2020

Date Inspected: 22/10/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming

Industrial Estate

Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3699P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Necessary	187.40 FL	*187.40 FL
3	2		*BOOT LID HINGE (LH/RH)	Not Necessary	142.60 FL	*- FL
4	2		*BOOT LID ABSORBER (LH/RH)	Not Necessary	173.40 FL	*- FL
5	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
6	1		*EMBLEM-HYBRID	Necessary	24.30 FL	*24.30 FL
7	1		*EMBLEM-IONIQ	Necessary	31.30 FL	*31.30 FL
8	1		*REAR SPOILER	Cut	665.40 FL	*665.40 FL
9	1		*BOOT LID LAMP LH	Broken	794.40 FL	*794.40 FL
10	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
11	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
12	1		*BOOT LID TRIMBOARD SIDE LH	Not Necessary	92.50 FL	*- FL
13	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
14	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
16	1		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	N/s Bent/O/s Not Necessary	376.20 FL	*188.10 FL
17	1		*ANTENNA ASSY-SMARTK	Not Necessary	689.50 FL	*- FL
18	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	47.50 FL	*- FL
19	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
20	1		*REAR BUMPER SIDE RETAINER LH	Broken	85.80 FL	*85.80 FL
21	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
22	1		*REAR BUMPER UNDER CENTRE	Not Necessary	123.85 FL	*- FL
23	1		*REAR BUMPER SIDE UNDER (LH)	Not Necessary	123.10 FL	*- FL
24	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
25	1		*REAR BUMPER REFLECTOR LAMP LH	Cut	82.90 FL	*82.90 FL
26	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
27	1		*REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	Not Necessary	328.60 FL	*- FL
28	1		*TAIL LAMP LH	Broken	870.40 FL	*870.40 FL
29	1		*TAIL LAMP QUARTER PANEL LH	Buckled	208.90 FL	*208.90 FL
30	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
31	1		*ANTENNA ASSY-TRUNK	Not Necessary	689.50 FL	*- FL
32	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
33	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
34	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
35	1		*SPARE TYRE PANEL	Not Necessary	892.50 FL	*- FL
36	1		*PANEL ASSY-REAR FLOOR SIDE (LH)	Not Necessary	39.40 FL	*- FL
37	1		*REAR TRAY TOOLS BOX LH	Not Necessary	693.20 FL	*- FL
38	1		*REAR FENDER LH	Buckled	1,768.30 FL	*1,768.30 FL
39	1		*REAR FENDER INNER PANEL LH	Dented	1,406.20 FL	*1,406.20 FL
40	1		*REAR FENDER SHIELD REAR PIECE LH	Torn	173.60 FL	*173.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR FENDER SHIELD FRT PIECE LH	Not Necessary	165.50 FL	*- FL
42	1		*REAR FENDER CORNER INNER UPPER GARNISH LH	Not Necessary	486.70 FL	*- FL
43	1		*REAR FENDER AIR-DUCT LH	Deformed	87.30 FL	*87.30 FL
44	1		*REAR FENDER TRIM BOARD LH	Bent	788.75 FL	*788.75 FL
45	1		*FUEL LID COVER LH	Serviceable	83.30 FL	*- FL
46	1		*FUEL LID GARNISH COVER	Not Necessary	361.20 FL	*- FL
47	1		*REAR FENDER TRIM BOARD TOP GARNISH LH	Not Necessary	167.90 FL	*- FL
48	1		*ASSY BSD BLIND SPOT RADAR LH	Broken	1,625.00 FL	*1,625.00 FL
49	1		*WIRING HARNESS BWS EXT	Not Necessary	988.90 FL	*- FL
50	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
51	1		*REAR TYRE RIM LH	Not Necessary	1,124.20 FL	*- FL
52	1		*REAR WHEEL HUP-CAP LH	Not Necessary	346.40 FL	*- FL
53	1		*REAR WHEELBEARING & HUB ASSY LH	Damaged	554.00 FL	*554.00 FL
54	1		*REAR TRAILING ARM LH	Distorted	265.40 FL	*265.40 FL
55	1		*REAR ASSIST LH	Distorted	227.90 FL	*227.90 FL
56	1		*REAR SHOCK ABSORBER LH	Distorted	230.50 FL	*230.50 FL
57	1		*REAR UPPER ARM LH	Distorted	239.50 FL	*239.50 FL
58	1		*REAR LOWER ARM LH	Distorted	393.10 FL	*393.10 FL
59	1		*REAR KNUCKLE ARM LH	Distorted	538.10 FL	*538.10 FL
60	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	35.00 FS	*35.00 FS
61	1		*BOOT LID COMFORT CABLINK & TEL NO STICKER	No such part	30.00 FS	*- FS
62	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
63	1		*SPARE TYRE PANEL TOP COVER SILICON	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,633.65	16,019.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,027.73	3,160.88
Total Parts (\$\$)	20,605.92	12,858.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	900.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	180.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
8	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
9	FOUR WHEEL ALIGNMENT	New	120.00	60.00
10	RE-SET FRT ABS SYSTEM	New	200.00	0.00
Gross Labour Cost (\$\$)			4,840.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >