Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011434/KPA3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100409306

Claimant
Vehicle No: SMF3835C

Insured Vehicle No: SKS5167P

Date of Loss: 16/10/2020 Nature of Claim: TP Claim No: 9161038164SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF3835C

Make & Model: HONDA CIVIC, 1.5 (A) Engine No: L15B72450688

Reg. Date: 22/05/2017 (Man. Year: 2017) Chassis No: MRHFC1660HT000040

Colour: Metallic Grey Odometer: 60556 km

Engine Capacity: 1498 cc Market Value/New Car

Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,540.88	1,797.84	743.04	29.24
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,580.00	420.00	1,160.00	73.42
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Nett	Amount (S\$)	4,120.88	2,217.84	1,903.04	46.18
+	Loss of Use (2.0 x \$	S\$60.00/day) (S\$)	120.00		
	+ Doo	c/Search Fee (S\$)	7.45		

INSPECTION

Date of Assignment: 20/10/2020

Date Inspected: 22/10/2020 Inspected At: Caris Autoworks Pte Ltd (HQ)

Nett Liability (S\$)

#05-03 160SIN MING DRIVE

Singapore 575722

2,345.29

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER (FRONT)	Bent / Cracked	579.90 FL	*579.90 FL
2	1		*BUMPER REINFORCEMENT (FRONT)	Repair	377.90 FL	*- FL
3	1		*BUMPER BRACKET (FRONT RIGHT)	Distorted	10.40 FL	*10.40 FL
4	1		*BUMPER FOG LAMP (FRONT RIGHT)	Serviceable	305.90 FL	*- FL
5	1		*BUMPER FOG LAMP GARNISH (FRONT RIGHT)	Cut	19.70 FL	*19.70 FL
6	1		*HEADLAMP (FRONT RIGHT)	Cut	1,299.80 FL	*1,299.80 FL
7	1		*AIR BAG SENSOR (FRONT RIGHT)	Dented	520.00 FL	*275.00 FL
8	1		*BODY CLIPS	Necessary	50.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	3,163.60	2,234.80
	- List Item Discount on L Items 20.00/20.00% (S\$)			622.72	436.96	
				Total Parts (S\$)	2,540.88	1,797.84
Report was unsubmitted during this print-out.						

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL KNOCKING	New	600.00	200.00
2	SPRAY PAINTING	New	800.00	220.00
3	WHEEL ALIGNMENT (COMPUTRISED)	New	100.00	0.00
4	WIRE CHECKING & DIAGNOSTIC	New	80.00	0.00
		Gross Labour Cost (S\$)	1,580.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >