Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20011436/QQF3Q2

Date: 10/12/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant SHB342H Insured Vehicle No: GZ6140U

Date of Loss: 21/10/2020 Nature of Claim: TP Claim No: CDMCG20001511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB342H

Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZRS099742

Reg. Date: 12/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403573237

Colour: Maroon Odometer: 257405 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm
Front Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 10,904.10 | 1,416.40 | 9,487.70 | 87.01 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,541.00 | 600.00 | 2,941.00 | 83.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 14,445.10 | 2,016.40 | 12,428.70 | 86.04 |
| Approved Total (Overridden) (S\$) | | 1,750.00 | | |
| Nett Amount (S\$) | 14,445.10 | 1,750.00 | 12,695.10 | 87.89 |

INSPECTION

Date of Assignment: 21/10/2020

Date Inspected: 21/10/2020 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

REPAIR DETAILS

| Reference | | | | |
|--|--|--|--|--|
| Part Source: MRM-SG | | Version: 1.0 (Last Synchronised: 10 Dec 2020) | | |
| Parts: | 144 | TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0) | | |
| Labour: | Repairer's | (Price-denominated Standard List) | | |
| Print Code: | (Unsubmitted, no print-code for SHB342H) | | | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | | | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | | | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|-------------|---|-------------|------------|-----------|
| 1 | 1 | | *NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%) | Necessary | 52.30 F | *39.23 F |
| 2 | 1 | | *NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%) | Necessary | 52.30 F | *39.23 F |
| 3 | 1 | | *EMBLEM SUB-ASSY REAR (DISC 25%) | Necessary | 46.30 F | *34.73 F |
| 4 | 1 | | *COVER,GUARD RR BUMPER (LOWER)(DISC 25%) | Scratched | 14.80 F | *11.10 F |
| 5 | 1 | | *GUARD,RR BUMPER,LOWER (DISC 25%) | Scratched | 558.30 F | *418.73 F |
| 6 | 1 | | *COVER,RR BUMPER ASSY (DISC 25%) | Crumpled | 423.90 F | *317.93 F |
| 7 | 1 | | *REAR BUMPER REINFORCEMENT (DISC 25%) | Bent | 318.80 F | *239.10 F |
| 8 | 1 | | *COVER,REAR FLOOR UNDER CENTER (DISC 25%) | Crumpled | 222.60 F | *166.95 F |
| 9 | 1 | | *SMRT LOGO (SN) | Necessary | 7.80 F | *7.80 F |
| 10 | 1 | | *STICKER DECAL 65558888 (SN) | Necessary | 21.60 F | *21.60 F |
| 11 | 2 | | *PIXEL STICKER (SN) | Necessary | 120.00 F | *120.00 F |
| 12 | 1 | | *WIRE,LUGGAGE ROOM | Serviceable | 143.50 F | *- F |
| 13 | 1 | | *ANTENNA,ELECTRICAL KEY | Serviceable | e 60.30 F | *- F |
| 14 | 1 | | *COVER,REAR FLOOR UNDER,LH | Serviceable | 234.30 F | *- F |
| 15 | 1 | | *COVER,REAR FLOOR UNDER,RH | Serviceable | e 169.50 F | *- F |
| 16 | 1 | | *COVER,REAR FLOOR UNDER CENTER | Serviceable | 222.60 F | *- F |
| 17 | 1 | | *TAIL GATE PANEL SUB-ASSY,BACK DOOR | Serviceable | 929.60 F | *- F |
| 18 | 1 | | *TAIL GATE LOCK ASSY BACK DOOR | Serviceable | 452.10 F | *- F |
| 19 | 1 | | *TAIL GATE LOCK COVER,BACK DOOR | Serviceable | 25.30 F | *- F |
| 20 | 1 | | *TAIL GATE WEATHERSTRIP BACK DOOR | Serviceable | 360.70 F | *- F |
| 21 | 1 | | *TAILGATE BOARD COVER | Serviceable | 24.10 F | *- F |
| 22 | 1 | | *TAILGATE BOARD ASSY | Serviceable | 251.50 F | *- F |
| 23 | 1 | | *LAMP SET STOP CENTER | Serviceable | 186.50 F | *- F |
| 24 | 1 | | *END PANEL SUBASSY,BODY LOWER BACK | Serviceable | 629.80 F | *- F |
| 25 | 1 | | *END PANEL,COVER DECK TRIM SERVICE HOLE | Serviceable | 47.00 F | *- F |
| 26 | 1 | | *END PANEL,COVER DECK TRIM REAR | Serviceable | 122.80 F | *- F |
| 27 | 1 | | *SEALANT SIKAFLEX | Serviceable | 37.00 F | *- F |
| 28 | 1 | | *SPARE TYRE PANEL,PAN REAR FLOOR | Serviceable | 564.80 F | *- F |
| 29 | 1 | | *LENS & BODY ASSY,RR BUMPER,RH | Serviceable | 486.80 F | *- F |
| 30 | 1 | | *PAD RR BUMPER,CTR | Serviceable | 2.20 F | *- F |
| 31 | 2 | | *STOPPER,RR BUMPER,RH & LH | Serviceable | 4.30 F | *- F |
| 32 | 1 | | *RETAINER,RR BUMPER,RH | Serviceable | 112.70 F | *- F |
| 33 | 1 | | *RETAINER,RR BUMPER,LH | Serviceable | 111.50 F | *- F |
| 34 | 1 | | *SENSOR REVERSE | Serviceable | 180.00 F | *- F |
| 35 | 1 | | *REAR BUMPER REINFORCEMENT | Serviceable | 318.80 F | *- F |
| 36 | 1 | | *FILLER,RR BUMPER RH | Serviceable | 119.90 F | *- F |
| 37 | 1 | | *FILLER,RR BUMPER LH | Serviceable | 119.90 F | *- F |
| 38 | 2 | | *SEAL RR BUMPER ARM,RH & LH | Serviceable | 11.00 F | *- F |
| 39 | 2 | | *PAD RR BUMPER RH & LH 3 | Serviceable | 3.80 F | *- F |
| 40 | 2 | | *PAD RR BUMPER RH & LH 2 | Serviceable | | *- F |
| 41 | 2 | | *PAD RR BUMPER RH & LH 1 | Serviceable | | *- F |
| | | | Report was unsubmitted during this print-out. | | | |
| | | | report was ansabilitied during this print-out. | | | |

Adjuster Report Page 3 of 4

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---|-------------|--|-------------------|------------|----------|
| 42 | 1 | | *CLIPS PIECE,FRT & RR BUMPER | Serviceable | 1.50 F | *- F |
| 43 | 1 | | *LENS & BODY ASSY,RR BUMPER LH | Repair | 486.80 F | *- F |
| 44 | 1 | | *TAIL GATE BACK DOOR OUTSIDE GARNISH SUB | Repair | 891.20 F | *- F |
| 45 | 1 | | *SPOILER SUB-ASSY REAR | Repair | 1,322.10 F | *- F |
| 46 | 1 | | *COVER,RR BUMPER ASSY | Repair | 423.90 F | *- F |
| F=Fra | ınchise | part. | | Total Parts (S\$) | 10,904.10 | 1,416.40 |
| | Report was unsubmitted during this print-out. | | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|---------------|------------|--------|
| Lab | our Items | | | |
| 1 | PANEL BEATING & BODY WORK | New | 845.00 | 200.00 |
| 2 | SPRAY PAINT | New | 2,016.00 | 380.00 |
| 3 | TO CHECK WIRING AND SYSTEM FUNCTION | New | 80.00 | 20.00 |
| 4 | TO TEST AND REFIX REVERSE SENSOR SYSTEM | New | 120.00 | 0.00 |
| 5 | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR | New | 120.00 | 0.00 |
| 6 | TO REMOVE AND REFIT WIRE HARDNESS | New | 200.00 | 0.00 |
| 7 | TO REPLACE SUNDRY PARTS | New | 100.00 | 0.00 |
| 8 | TO WASH AND VACUUM | New | 60.00 | 0.00 |
| | Gross Labo | ur Cost (S\$) | 3,541.00 | 600.00 |
| | | | | |

< END OF ESTIMATES >

Report was unsubmitted during this print-out.