



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC20011438/T1vf3e2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 25-11-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 2608E	Veh. Inspected	SJE 5918A
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VC00/023800	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	21/10/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ACU300050723	Colour	BLACK
Odometer	214075	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R18	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R18	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R18	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R18	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/10/2020	Inspection Date	23/10/2020
Survey held at	VFIX AUTO SERVICE PTE LTD 26 CHIA PING ROAD SINGAPORE 619977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------