

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6502M**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	I40VC COVER ASSY-RR BUMPE	DENTED	1,106.00	1,106.00
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40VC COVER-RR BUMPER LWR	NOT NECESSARY	228.00	-
	LESS 20% DISCOUNT		-271.20	-225.60
			1,084.80	902.40
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		300.00	280.00
	SPRAYPAINT CHARGE.		300.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			680.00	510.00
<b>GRAND TOTAL</b>			<b>1,764.80</b>	<b>1,412.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,150.00</b>

Report Ref No. NS/INC20011441/Eqf3e2


**CHEN TSUE YEE**

Automotive Assessor


**K.K.LAU CPT(RET)**
**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**
**REGD Auto Consultant-SAE, Licensed Appraiser**
**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**