

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20011441/Eqf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	04-11-2020 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJN 9401A	Veh. Inspected		SHD 6502M
	Policy No.	5116523100	Coverage (\$)		0.00
	Claim No.	MT/1108859-001	Exces	s (\$)	0.00
	Assign From		Assig	n Date	21/10/2020
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2014
	Chassis No.	KMHLB41UMEU059654	Colou	r	BLUE
	Odometer	741719	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	FIREST	TONE	5 mm
	L/H Front Tyre	205/60 R16	FIRESTONE		5 mm
	R/H Rear Tyre	205/60 R16	FIRESTONE		5 mm
	L/H Rear Tyre	205/60 R16	FIRESTONE		5 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/10/2020	Inspection Date 21/10/2020		
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
	59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				