Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011442/UQF3Q2

2NR8729485

Date: 03/11/2020

REFERENCE

China Taiping

Handling Insurer: Insurance (Singapore) Policy No: DMCVSNW00043162002

Pte. Ltd.

Claimant

SLP6002D

Insured

Vehicle No : GBH5169Z Vehicle No:

Nature of SNM20D203719/C02/CHUAKK Date of Loss: TP 03/10/2020 Claim:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP6002D**

TOYOTA COROLLA AXIO, 1.5 CVT ABS D/AIRBAG Engine No: Make & Model:

2WD (A)

Reg. Date: 12/06/2017 (Man. Year: 2016) Chassis No: NRE1610025477

Colour: Odometer: 273677 km White

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Front Left Side: Rear Left Side: Firenza 6 mm Firenza 6 mm Front Right Side: Rear Right Side: Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,313.90	1,739.85	574.05	24.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	520.00	800.00	60.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,633.90	2,259.85	1,374.05	37.81
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,633.90	1,800.00	1,833.90	50.47
+ GST 7.00/7.00% (S\$)	254.37	126.00	128.37	50.47
Nett Amount (S\$)	3,888.27	1,926.00	1,962.27	50.47

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 22/10/2020 Inspected At: Focus Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #02-48/50 Autobay

Singapore 417883

Estimated Period of Repair: 2.0 days

Manager: SHIAU CHAN Adjuster: MARCUS CHUA

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2020)		
Parts:	143	TOYOTA COROLLA AXIO 1.5 CVT ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SLP6002D)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT HEADLAMP-RH	Cracked	986.20 FL	*767.30 FL	
2	1		*FRONT GRILLE	Cracked	386.40 FL	*386.40 FL	
3	1		*FRONT GRILLE MOULDING	Serviceable	298.40 FL	*- FL	
4	1		*FRONT BUMPER	Dented	867.40 FL	*867.40 FL	
5	1		*FRONT BUMPER SIDE RETAINER-RH	Not Necessary	48.40 FL	*- FL	
6	1		*FRONT BUMPER CENTRE GRILLE	Distorted	498.40 FL	*298.70 FL	
F=Franchise part. L=ListItemDisc.							
				Sub Total (S\$)	3,085.20	2,319.80	
			- List Item Discount on L Items	s 25.00/25.00% (S\$)	771.30	579.95	
				Total Parts (S\$)	2,313.90	1,739.85	

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	680.00	250.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	0.00
4	SPRAY PAINTING	New	520.00	250.00
		Gross Labour Cost (S\$)	1,320.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >