

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20011443/R1PA3Q2

**Date:** 15/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900262259

**Claimant**  
**Vehicle No :** SJU6279U **Insured Vehicle No :** SMR5866L

Date of Loss: 21/10/2020 Nature of Claim: TP Claim No: 9705160608SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU6279U		
Make & Model:	BMW X3, 2.0 I SDRIVE (A)	Engine No:	F2593317B48B20A
Reg. Date:	26/09/2019 (Man. Year: 2019)	Chassis No:	WBATR12030LS31234
Colour:	White	Odometer:	12174 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,339.40	1,649.40	1,690.00	50.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,829.40</b>	<b>3,583.40</b>	<b>2,246.00</b>	<b>38.53</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	408.06	250.84	157.22	38.53
<b>Nett Amount (\$\$)</b>	<b>6,237.46</b>	<b>3,834.24</b>	<b>2,403.22</b>	<b>38.53</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,136.24</b>		

### INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 02/11/2020 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Serviceable	743.50 FS	*- FS
3	1		*LH SIDE GUIDE FOR BUMPER	Serviceable	58.25 FS	*- FS
4	1		*RH SIDE GUIDE FOR BUMPER	Serviceable	58.25 FS	*- FS
5	1		*LH BUMPER GUIDE	Serviceable	61.35 FS	*- FS
6	1		*RH BUMPER GUIDE	Serviceable	61.35 FS	*- FS
7	1		*REAR BUMPER BOTTOM REINFORCEMENT	Serviceable	78.85 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (X LINER PM)	Deformed	1,555.40 FS	*1,555.40 FS
9	1		*REAR BUMPER CLADDING (PDC)	Serviceable	608.05 FS	*- FS
10	4		*DECOUPING RING PDC TORQUE CONVERTER	Serviceable	20.40 FS	*- FS
11	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
				<b>Total Parts (\$\$)</b>	<b>3,339.40</b>	<b>1,649.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER PANEL AND ATTACHMENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR ECTION FOR PROPER FUNCTION	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,490.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >