Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20011445/KQF3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1800034514 Policy No: Claimant Insured Vehicle No: SDQ9685C FX8202J Vehicle No:

Date of Loss: 27/09/2020 Nature of Claim: ΤP Claim No: 2195359185SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

FX8202J Reg No:

Engine No: Make & Model: HONDA WAVE 125, 125cc NF125MDE0090342 Reg. Date: 10/03/2004 (Man. Year: 2003) Chassis No: NF125MD0090342 Odometer: 92732 km

Colour: Blue

Engine Capacity: 125 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Rear Tyre Size: Front Tyre Size: 70/90 R17 80/90 R17 Rear Left Side: Front Left Side: Maxxis 4 mm Maxxis 4 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,039.49	3,425.20	2,614.29	43.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	265.00	765.00	74.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,069.49	3,690.20	3,379.29	47.80
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	7,069.49	2,600.00	4,469.49	63.22

INSPECTION

Date of Assignment: 21/10/2020

Date Inspected: 22/10/2020 Inspected At: Serve You Motor Service (HQ)

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265

Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

R	6	_	\cap	m	n	16	n	Ы	6	Ы	P	a	rts
١٦	◡	U	u			ıC	ш	ıu	ᆫ	u		а	LO

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BRAKE LEVER	Serviceable	42.00 FL	*- FL	
2	1		*BRAKE PEDAL	Bent	48.00 FL	*48.00 FL	
3	1		*CENTRE COWLING	Cracked	188.00 FL	*188.00 FL	
4	1		*CENTRE INNER COVER	Cracked	182.00 FL	*182.00 FL	
5	1		*FORK ASSY LH	Bent	420.00 FL	*420.00 FL	
6	1		*FORK UNDER BRACKET	Distorted	189.00 FL	*189.00 FL	
7	1		*FRONT BRAKE DISC	Warped	165.00 FL	*165.00 FL	
8	1		*FRONT BRAKE RESERVOIR TANK	Serviceable	145.00 FL	*- FL	
9	1		*FRONT MUDGUARD	Buckled	95.00 FL	*95.00 FL	
10	1		*FRONT FOOTREST BRACKET	Distorted	95.00 FL	*95.00 FL	
11	1		*FRONT FOOTREST RUBBER LH	Torn	28.00 FL	*28.00 FL	
12	1		*FRONT WHEEL RIM	Dented	450.00 FL	*450.00 FL	
13	1		*FRONT WHEEL RIM SHAFT	Serviceable	45.00 FL	*- FL	
14	1		*HANDLE BAR ASSY	Bent	126.00 FL	*126.00 FL	
15	1		*HANDLE BAR END LH	Bent	58.00 FL	*58.00 FL	
16	1		*HANDLE BAR GRIP LH	Serviceable	28.00 FL	*-FL	
17	1		*HEADLAMP ASSY	Serviceable	280.00 FL	*- FL	
18	1		*HEADLAMP BRACKET	Repair	77.10 FL	*- FL	
19	1		*HEADLAMP COWLING	Cracked	120.00 FL	*120.00 FL	
20	1		*METER ASSY	Serviceable	320.00 FL	*-FL	
21	1		*METER COVERING SET	Serviceable	85.00 FL	*- FL	
22	1		*FRONT SIDE MIRROR ASSY LH	Serviceable	328.00 FL	*- FL	
23	1		*REAR EXHAUST MUFFLER PROTECTOR	Dented	185.00 FL	*185.00 FL	
24	1		*REAR FOOTREST BRACKET LH	Bent	85.00 FL	*85.00 FL	
25	1		*REAR FOOTREST LH	Torn	45.00 FL	*45.00 FL	
26	1		*REAR SIDE BOARD LH	Serviceable	115.00 FL	*-FL	
27	1		*REAR TAILBOARD	Serviceable	165.00 FL	*- FL	
28	1		*REAR TAILLAMP	Serviceable	128.00 FL	*- FL	
29	1		*SIDE FAIRING LH	Cracked	289.00 FL	*289.00 FL	
30	1		*STEERING CONE	Necessary	85.00 FL	*85.00 FL	
31	1		*STEERING STEM	Bent	165.00 FL	*165.00 FL	
32	1		*SIDE FAIRING INNER COVER LH	Serviceable	150.00 FL	*-FL	
33	1		*GEAR PEDAL	Repair	58.00 FL	*-FL	
34	1		*CLUTCH LEVER	No such part	42.00 FL	*-FL	
35	1		*SIDE FAIRING SIGNAL LAMP LH	Serviceable	180.00 FL	*- FL	
36	1		*REAR EXHAUST MUFFLER (LOCAL REPAIR)	Dented	432.00 FS	*120.00 FS	
37	1		*BODY STICKER SET	Necessary	180.00 FS	*180.00 FS	
38	1		*ERP IU UNIT	Serviceable	160.00 FS	*-FS	
39	1		*FRONT FORK OIL SEAL LH	Necessary	24.00 FS	*24.00 FS	
40	1		*FRONT NUMBER PLATE (STICKER)	Bent	25.00 FS	*12.00 FS	
41	1		*REAR BOX ASSY	Cut	250.00 FS	*250.00 FS	
42	1		*REAR BOX STAY SET	Repair	160.00 FS	*-FS	
43	1		*STEERING CONE BEARING	Necessary	65.00 FS	*65.00 FS	
44	1		*FRONT RIM WHEEL BEARING	Necessary	58.00 FS	*58.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
Sub Total (S\$)				6,560.10	3,727.00		
			- List Item Discount on L Items	10.00/10.00% (S\$)	520.61	301.80	
				Total Parts (SA)	6,039.49	3 425 20	
				Total Parts (S\$)	0,039.43	3,425.20	

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=... 18/11/2020

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING (TO FR)	New	30.00	15.00
2	TO CARRY OUT BODY FRAME ALIGNMENT	New	250.00	100.00
3	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	350.00	150.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS ON AFFECTED AREAS	New	400.00	0.00
	Gross Labo	our Cost (S\$)	1,030.00	265.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >