

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 959Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	BROKEN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	NOT NECESSARY	99.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	438.40	-
1	FRONT BUMPER BRACKET TOP RH	BROKEN	22.40	22.40
1	FRONT BUMPER BRACKET (RH)	BROKEN	24.60	24.60
1	FRONT BUMPER GRILLE RH	BROKEN	93.60	93.60
1	HEADLAMP (RH)	BROKEN	1,388.00	1,388.00
1	FRONT BUMPER PROTECTOR RH	NOT NECESSARY	25.40	-
1	FRONT BUMPER RETAINER MOUTING RH	NOT NECESSARY	9.20	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	FRONT FENDER (RH)	DENTED	663.00	663.00
1	FRONT FENDER SHIELD (RH)	TORN	174.90	174.90
1	WIPER CONTAINER	NOT NECESSARY	61.90	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	2,265.90	-
	LESS 20% DISCOUNT		-1,445.22	-865.22
			5,780.88	3,460.88
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET.		600.00	560.00
	SPRAY PAINTING.		800.00	600.00
	CHECK WIRING.		60.00	30.00
	TUFF KOTE.		60.00	30.00
			-	-
			-	-
			-	-
			1,520.00	1,220.00
	GRAND TOTAL		7,300.88	4,680.88

Report Ref No. NS/INC20011446/Evd3q2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,750.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC20011446/Evd3q2



CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser