



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20011451/Ktf3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 11-11-2020



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|------------------|-----------------------|------------|
| Insured Veh. | XD 2097C | Veh. Inspected | SJP 5750H |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | CLMOMVC000003898 | Excess (\$) | 0.00 |
| Assign From | SHERY WONG | Assign Date | 21/10/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|--------------------|---------------------|--------------------|
| Make & Model | HYUNDAI AVANTE (A) | c.c | 1591 |
| Engine No. | HIDDEN | Year of Reg. | 2009 |
| Chassis No. | KMH DU41BR9U712872 | Colour | METALLIC RED |
| Odometer | 237872 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | NEXEN | 3 mm |
| L/H Front Tyre | 195/65 R15 | NEXEN | 3 mm |
| R/H Rear Tyre | 195/65 R15 | NEXEN | 2 mm |
| L/H Rear Tyre | 195/65 R15 | NEXEN | 2 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 20/10/2020 | Inspection Date | 22/10/2020 |
| Survey held at | S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|--|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 9 Working Days |
|--|-----------------------|