

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011453/KTD3Q2

Date: 08/01/2021

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN30651619011

Claimant  
Vehicle No : SJU81LInsured  
Vehicle No : SJY5577U

Date of Loss: 17/10/2020

Nature of  
Claim: TPClaim  
No: SNM20D203943/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU81L

Make &amp; Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZF300466

Reg. Date: 23/10/2009 (Man. Year: 2009)

Chassis No: ACR500098949

Colour: Metallic Pearl White

Odometer: 202211 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55R17

Rear Tyre Size: 215/55R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,362.75	4,235.05	6,127.70	59.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	1,890.00	2,640.00	58.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,892.75</b>	<b>6,125.05</b>	<b>8,767.70</b>	<b>58.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
<b>(S\$)</b>	14,892.75	4,900.00	9,992.75	67.10
<b>+ GST 7.00/7.00% (S\$)</b>	1,042.49	343.00	699.49	67.10
<b>Nett Amount (S\$)</b>	<b>15,935.24</b>	<b>5,243.00</b>	<b>10,692.24</b>	<b>67.10</b>

### INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 21/10/2020 Inspected At:

AERO GARAGE PTE LTD  
BLK 160, SIN MING DRIVE,  
#08-07  
SIN MING AUTOCITY  
SINGAPORE 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2021)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJU81L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted/Mtg Cracked	880.45 F	*715.10 FL
2	2		*REAR BUMPER BRACKETS	Repair	103.10 F	*- FL
3	1		*REAR BUMPER RETAINERS	O/s Distorted	110.20 F	*55.10 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
5	1		*REAR FENDER RH	Bent	806.75 F	*806.75 FL
6	1		*REAR FENDER INNER SHIELD RH	Serviceable	113.50 F	*- FL
7	1		*REAR FENDER INNER SIDE TRIM RH	Serviceable	806.10 F	*- FL
8	1		*SIDE DOOR RH	Bent	1,410.35 F	*1,302.80 FL
9	1		*SIDE DOOR CHROME MOULDING RH	Scratched	201.20 F	*201.20 FL
10	1		*SIDE DOOR WEATHERSTRIP RH	Serviceable	393.40 F	*- FL
11	1		*SIDE DOOR OUTER HANDLE RH	Serviceable	210.40 F	*- FL
12	1		*SIDE DOOR LOCK RH	Repair	509.10 F	*- FL
13	1		*SIDE DOOR REGULATOR RH	Serviceable	393.10 F	*- FL
14	1		*SIDE DOOR INNER HANDLE RH	Serviceable	110.45 F	*- FL
15	1		*SIDE DOOR INNER TRIM BOARD RH	Serviceable	606.10 F	*- FL
16	2		*SIDE DOOR HINGES RH	Repair	110.40 F	*- FL
17	1		*ROCKER PANEL RH	Repair	545.10 F	*- FL
18	1		*REAR WHEEL BEARING RH	Necessary	695.45 F	*375.20 FL
19	1		*REAR AXLE RH	Bent	2,017.60 F	*1,817.25 FL
20	1		*REAR WHEEL RIM RH	Dented	300.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,362.75</b>	<b>5,563.40</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	1,328.35
<b>Total Parts (\$\$)</b>	<b>10,362.75</b>	<b>4,235.05</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGE TO REMOVE.CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS	New	2,000.00	800.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	750.00
3	TO REMOVE,REPLACE SIDE DOOR FITTINGS TO FACILITATE REPAIR	New	300.00	60.00
4	TO REMOVE,REPLACE DOOR WINDSCREEN GLASS	New	150.00	60.00
5	TO REMOVE,REPLACE REAR WHEEL BEARING AND AXLE	New	500.00	200.00
6	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,530.00</b>	<b>1,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >