



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 301Y

| Qty                                | Description of Parts   | Condition                      | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|--------------------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |                                |                           |                   |
| 1                                  | REAR TAILGATE PANEL (CONSISTENT)   | TO REPAIR SEE LABOUR           | 2,150.00                  | -                 |
| 1                                  | RHS PANEL (CONSISTENT)   | DENTED / BENT                  | 2,850.00                  | 2,450.00          |
| 1                                  | REAR TAILGATE HINGES (CONSISTENT)  | NOT NECESSARY                  | 250.00                    | -                 |
| 1                                  | REAR TAILLAMPS RHS (CRACKED)   | NOT CONSISTENT WITH THE IMPACT | 598.00                    | -                 |
| 1                                  | REAR TAILLAMPS BRACKET RHS (CONSISTENT)  | NOT NECESSARY                  | 122.00                    | -                 |
| 1                                  | RHS CORNER BRACKET (CONSISTENT)  | BENT                           | 320.00                    | 181.00            |
| 1                                  | RHS CORNER BRACKET STOPPER (CONSISTENT)  | MISSING                        | 60.00                     | 60.00             |
| 1                                  | RHS MUD GUARD (CONSISTENT)   | DEFORMED                       | 125.00                    | 125.00            |
| 1                                  | REAR EXHAUST PIPE ASSY (CONSISTENT)  | NOT NECESSARY                  | 2,310.00                  | -                 |
|                                    | LESS 25% DISCOUNT  |                                | -2,196.25                 | -704.00           |
|                                    |  |                                | 6,588.75                  | 2,112.00          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |                                |                           |                   |
| 1                                  | RHS PANEL COMPANY STICKER (SN) (CONSISTENT)  | NECESSARY                      | 450.00                    | 250.00            |
| 1                                  | 13 PAX STICKER (SN) (CONSISTENT)   | NECESSARY                      | 20.00                     | 10.00             |
|                                    | 70KM/H STICKER (SN) (CONSISTENT)   | NECESSARY                      | 20.00                     | 10.00             |
|                                    |  |                                | 490.00                    | 270.00            |
| <b><u>LABOUR</u></b>               |  |                                |                           |                   |
|                                    | TO REMOVE THE AFFECTED PARTS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR TAILGATE PANEL . |                                | 1,000.00                  | 300.00            |
|                                    | TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON REPAIRED AREAS .                                    |                                | 800.00                    | 430.00            |
|                                    | TO REMOVE AND REFIX WIRING .   | NOT NECESSARY                  | 120.00                    | -                 |
|                                    | TO REMOVE AND REPLACE EXHAUST PIPE ASSY .  | NOT NECESSARY                  | 250.00                    | -                 |
|                                    | TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS .   |                                | 250.00                    | 30.00             |
|                                    |  |                                | 2,420.00                  | 760.00            |
| <b>GRAND TOTAL</b>                 |  |                                | <b>9,498.75</b>           | <b>3,142.00</b>   |



|   |  |  |                 |
|---|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>2,500.00</b> |
|---|--|--|-----------------|

Report Ref No. CC4/ASM20011457/Uba3q2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**