

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20011460/ABA3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015	
Claimant Vehicle No : SJN5828D	Insured Vehicle No : SHD3142M	
Date of Loss: 20/10/2020	Nature of Claim: TP	Claim No: MCT20100344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN5828D		
Make & Model: HYUNDAI AVANTE, 1.6 HD (A)	Engine No: G4FC9U603028	
Reg. Date: 23/02/2009 (Man. Year: 2009)	Chassis No: KMH DU41BR9U688844	
Colour: Grey	Odometer: 166001 km	
Engine Capacity: 1591 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15	Rear Tyre Size: 185/65R15	
Front Left Side: Yokohama 6 mm	Rear Left Side: Yokohama 6 mm	
Front Right Side: Yokohama 6 mm	Rear Right Side: Yokohama 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,290.00	7,532.24	3,757.76	33.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	2,280.00	2,430.00	51.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,000.00	9,812.24	6,187.76	38.67
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	16,000.00	7,800.00	8,200.00	51.25
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/10/2020		
Date Inspected: 21/10/2020	Inspected At:	Cn Motor (HQ) 1 Kaki Bukit Ave 6 Blk C #01-41 Autobay Singapore 417883
Estimated Period of Repair: 9.0 days		

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2021)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN5828D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H HEAD LAMP	Cracked	463.80 F	*463.80 FL
2	1		*FRONT L/H HEAD LAMP LOWER BRACKET	Not Necessary	32.00 F	*- FL
3	1		*FRONT L/H FENDER	Distorted	396.70 F	*396.70 FL
4	1		*FRONT L/H FENDER COWLING	Torn	53.60 F	*53.60 FL
5	10		*FRONT L/H FENDER COWLING CLIP	Necessary	65.00 F	*30.00 FL
6	1		*FRONT BUMPER	Distorted	428.00 F	*428.00 FL
7	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
8	1		*FRONT L/H BUMPER SIDE RETAINER	Cracked	33.00 F	*33.00 FL
9	1		*FRONT L/H BUMPER FOG LAMP	Cracked	136.20 F	*136.20 FL
10	1		*FRONT L/H LOWER ARM	Bent	305.00 F	*305.00 FL
11	1		*FRONT L/H KNUCKLE ARM	Damaged	280.00 F	*280.00 FL
12	1		*FRONT L/H KNUCKLE ARM BEARING	Damaged	98.00 F	*98.00 FL
13	1		*FRONT L/H SHOCK ABSORBER	Bent	298.00 F	*298.00 FL
14	1		*FRONT L/H STABILIZER BAR	Bent	38.00 F	*38.00 FL
15	1		*FRONT L/H DRIVE SHAFT	Not Necessary	727.10 F	*- FL
16	1		*FRONT STEERING RACK	Bent	1,328.00 F	*1,328.00 FL
17	1		*FRONT L/H SIDE MIRROR ASSY	Not Necessary	628.80 F	*- FL
18	1		*FRONT L/H DOOR	Dented	989.60 F	*989.60 FL
19	2		*FRONT L/H DOOR HINGE	Not Necessary	92.40 F	*- FL
20	2		*FRONT L/H DOOR FRAME STICKER	Necessary	56.80 F	*56.80 FL
21	1		*FRONT SUPPORT PANEL	Cracked	753.00 F	*753.00 FL
22	1		*FRONT BUMPER REINFORCEMENT	Bent	239.60 F	*239.60 FL
23	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	109.60 F	*109.60 FL
24	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	74.40 F	*- FL
25	1		*FRONT CROSSMEMBER	Bent	2,598.40 F	*2,598.40 FL
26	1		*FRONT L/H RIM	Cut	650.00 FS	*400.00 FS
27	1		*FRONT L/H TYRE	Punctured	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,290.00	9,265.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,733.06
Total Parts (\$\$)	11,290.00	7,532.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT L/H DOOR & DOOR COMPONENTS	New	280.00	80.00
2	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE	New	380.00	300.00
3	TO REMOVE & REFIT FRONT L/H DRIVE SHAFT & STEERING RACK	New	450.00	150.00
4	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
5	TO CHECK WIRING	New	100.00	30.00
6	TUFF KOTE	New	150.00	40.00
7	PANEL BEATING	New	1,600.00	1,000.00
8	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (S\$)			4,710.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >