

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

21/10/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111
Inspector.

Accident date: 20-10-2020

Estimated repair cost for vehicle no: SJN5828D HYUNDAI AVANTE 1.6 A '09

CHASSIS: KMH DU41BR9U688844

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Front L/H Head Lamp <i>Cracked</i>		\$463.80	✓
2	1	Front L/H Head Lamp Lower Bracket <i>Not ne</i>		\$32.00	x
3	1	Front L/H Fender <i>Distorted</i>		\$396.70	✓
4	1	Front L/H Fender Cowling <i>torn</i>		\$53.60	✓
5	10	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$65.00	30
6	1	Front Bumper <i>Distorted</i>		\$428.00	✓
7	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00	30
8	1	Front L/H Bumper Side Retainer <i>cracked</i>		\$33.00	✓
9	1	Front L/H Bumper Fog Lamp <i>Cracked</i>		\$136.20	✓
10	1	Front L/H Rim <i>lit</i>		\$650.00	400/sal
11	1	Front L/H Tyre <i>Punctured</i>		\$350.00	200/sal
12	1	Front L/H Lower Arm <i>Bent</i>		\$305.00	✓
13	1	Front L/H Knuckle Arm <i>Damaged</i>		\$280.00	✓
14	1	Front L/H Knuckle Arm Bearing <i>Damaged</i>		\$98.00	✓
15	1	Front L/H Shock Absorber <i>Bent</i>		\$298.00	✓
16	1	Front L/H Stabilizer Bar <i>Bent</i>		\$38.00	✓
17	1	Front L/H Drive Shaft <i>Not ne</i>		\$727.10	x
18	1	Front Steering Rack <i>Bent</i>		\$1,328.00	✓
19	1	Front L/H Side Mirror Assy <i>new</i>		\$628.80	x
20	1	Front L/H Door <i>Dented</i>		\$989.60	✓
21	2	Front L/H Door Hinge <i>new</i>	\$46.20	\$92.40	x
22	2	Front L/H Door Frame Sticker <i>new</i>	\$28.40	\$56.80	✓

Subtotal:- \$7,515.00

4964.70

SN 1600

3971.76

Labour charges

To remove & refit front L/H door & door components	\$280.00 80
To remove & refit front L/H undercarriage	\$380.00 300
To remove & refit L/H drive shaft & steering rack	\$450.00 150.
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
Tuff kote	\$150.00 40.
Panel beating	\$1,600.00 1000.
Spray painting	\$1,600.00 600.

Subtotal:- \$4,710.00

Total:- \$12,225.00

2280

Supplementary: 2960.48

total: 9812.24

4/5: 7.8K.

09 Days

7.8K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

21-10-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 20-10-2020

Supplementary repair cost for vehicle no: SJN5828D HYUNDAI AVANTE 1.6 A '09

CHASSIS: KMH DU41BR9U688844

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Support Panel <i>Cracked.</i>		\$753.00 ✓
2	1	Front Bumper Reinforcement <i>Bent</i>		\$239.60 ✓
3	1	Front Bumper Reinforcement Foam <i>Cracked.</i>		\$109.60 ✓
4	1	Front Bumper Fog Lamp Cover <i>Not me</i>		\$74.40 x.
5	1	Front Crossmember <i>Bent.</i>		\$2,598.40 ✓

Subtotal:- \$3,775.00

370060

2960.48