



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107045

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/10/2021
Reference CC6/CTI20011464/Kga3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBE 9189E
Insured Veh. GBG 7015B
Claim No. SNM20D203971
Policy No. DMCVSNA00088882003
Accident Date 19/10/2020
Inspection Date 20/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20011464/Kga3q2	
			Date: 12/10/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 7015B	Veh. Inspected	GBE 9189E	
Policy No.	DMCVSNA00088882003	Coverage (\$)	0.00	
Claim No.	SNM20D203971	Excess (\$)	0.00	
Assign From		Assign Date	20/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFAT35Y10K206242	Colour	ORANGE / BLUE	
Odometer	225667 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	3 mm	
L/H Front Tyre	195 R15X8	MICHELIN	3 mm	
R/H Rear Tyre	155 R12X8 (D)	FALKEN	7/7 mm	
L/H Rear Tyre	155 R12X8 (D)	FALKEN	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/10/2020	Inspection Date	20/10/2020	
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9189E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,337.00	1,265.00
1	REAR DECK END PANEL	BENT	848.00	848.00
1	LH TAILLAMP BRACKET	BENT	183.40	175.00
2	TAILLAMP	O/S SERVICEABLE / N/S CRACKED	528.40	264.20
1	REAR NUMBER PLATE BRACKET	TO REPAIR SEE LABOUR	145.10	-
1	REAR NUMBER PLATE LAMP	SERVICEABLE	69.00	-
1	REAR LOWER SPARE TYRE CARRIER CHAIN	TO REPAIR SEE LABOUR	254.00	-
1	REAR LH SIDE GATE	BENT	1,337.00	1,337.00
1	REAR LH SIDE GATE LOWER LOCK CATCH	DISTORTED	54.10	54.10
1	REAR LH SIDE LOWER RUBBER STOPPER BRACKET	BENT	123.10	123.10
1	SET REAR SIDE LOWER RUBBER STOPPER	SERVICEABLE	69.10	-
	LESS 25% DISCOUNT		-1,237.05	-1,016.60
			3,711.15	3,049.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	SERVICEABLE	45.00	-
1	REVERSE SENSORS (SN)	SHORTED	350.00	200.00
1	REAR TAILGATE INNER METAL PROTECTION PANEL (SN)	BUCKLED	600.00	420.00
1	SET REAR TAILGATE /REAR LH SIDE GATE STICKER (SN)	NECESSARY	650.00	500.00
1	REAR TAILGATE '13 PAX' STICKER (SN)	NECESSARY	15.00	12.00
1	REAR TAILGATE '70 KM/H' STICKER (SN)	NECESSARY	15.00	12.00
			1,675.00	1,144.00
<u>LABOUR</u>				
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES .INCLUSIVE OF THE REPAIR OF REAR NUMBER PLATE BRACKET AND REAR LOWER SPARE TYRE CARRIER CHAIN .		1,100.00	800.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		1,200.00	800.00
	TO CHECK WIRINGS & LIGHTINGS.		40.00	20.00

Report Ref No. CC6/CTI20011464/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE ,REFIT REVERSE SENSORS.		60.00	50.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT .		80.00	60.00
			2,480.00	1,730.00
GRAND TOTAL			7,866.15	5,923.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CC6/CTI20011464/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 9189E

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 9189E

RE-INSPECTION

