Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011465/QBA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100373502

Claimant
Vehicle No: Insured Vehicle No: GBD713G

Date of Loss: 19/10/2020 Nature of Claim: TP Claim No: 8174722507SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM2488R

Make & Model: TOYOTA PRIUS PLUS, 1.8 (A) Engine No: 2ZR0D09385

Reg. Date: 24/06/2019 (Man. Year: 2018) Chassis No: JTDZS3EUX0J038344

Colour: Black Odometer: 132554 km

Engine Capacity: 1798 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm
Front Right Side: Davanti 6 mm
Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|---------------------|------------|------------|--------|
| Parts | 4,631.25 | 1,440.75 | 3,190.50 | 68.89 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,150.00 | 900.00 | 1,250.00 | 58.14 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 6,781.25 | 2,340.75 | 4,440.50 | 65.48 |
| Approved Total (Overridden) (S\$) | | 1,850.00 | | |
| (S\$) | 6,781.25 | 1,850.00 | 4,931.25 | 72.72 |
| + GST 7.00/7.00% (S\$) | 474.69 | 129.50 | 345.19 | 72.72 |
| Nett Amount (S\$) | 7,255.94 | 1,979.50 | 5,276.44 | 72.72 |
| + Loss of Use (5.0 x S\$1 | 20.00/day) (S\$) | 600.00 | | |
| + Doc/S | Search Fee (S\$) | 36.49 | | |
| Ne | ett Liability (S\$) | 2,615.99 | | |
| Global Sum | Settlement (S\$) | 2,450.00 | | |

INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 28/10/2020 Inspected At: My Car Consultant Pte Ltd (HQ)

60 Jalan Lam Huat,, Carros Centre

#05-67/68

Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

| 1 | No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|--|--|---|----------|-----------------------------------|-------------------|------------|------------|--|
| Terms | 1 | 1 | | *REAR BUMPER | Crumpled | 798.00 FL | *698.00 FL | |
| 4 1 *REAR BUMPER SIDE RETAINER RH Serviceable 65.00 FL *-FL 5 1 *REAR BUMPER LOWER Scratched 351.00 FL *351.00 FL *351.00 FL *351.00 FL *15.00 FL *112.00 FL *12.00 FL *55.00 FL *5.00 FL *12.00 FL *498.00 FL *12.00 FL *12.00 FL *498.00 FL | 2 | 1 | | *REAR BUMPER BRACKET LH | Serviceable | 68.00 FL | *- FL | |
| 5 1 *REAR BUMPER LOWER Scratched 351.00 FL *351.00 FL *351.00 FL *12.00 FL *112.00 FL *12.00 FL *2.00 FL *2.00 FL *2.00 FL *498.00 FL *498.00 FL *85.00 FL *85.00 FL *85.00 FL *85.00 FL *85.00 FL *85.00 FL *2.00 FL </td <td>3</td> <td>1</td> <td></td> <td>*REAR BUMPER SIDE RETAINER LH</td> <td>Broken</td> <td>65.00 FL</td> <td>*65.00 FL</td> | 3 | 1 | | *REAR BUMPER SIDE RETAINER LH | Broken | 65.00 FL | *65.00 FL | |
| 6 1 *REAR BUMPER REFLECTOR LH Cracked 112.00 FL *112.00 FL 7 1 *REAR BUMPER REINF Serviceable 398.00 FL *-FL 8 1 *REAR BUMPER SPONGE Serviceable 187.00 FL *-FL 9 1 *REAR TAILLAMP LH Crumpled 498.00 FL *498.00 FL *498.00 FL **50.0 FL **50.00 FL **5 | 4 | 1 | | *REAR BUMPER SIDE RETAINER RH | Serviceable | 65.00 FL | *- FL | |
| 7 1 *REAR BUMPER REINF Serviceable 398.00 FL *-FL 8 1 *REAR BUMPER SPONGE Serviceable 187.00 FL *-FL 9 1 *REAR TAILLAMP LH Crumpled 498.00 FL *498.00 FL 10 1 *REAR TAILLAMP LOWER BRACKET LH Broken 85.00 FL *85.00 FL 11 1 *REAR TAILLAMP LOWER PANEL LH Repair 298.00 FL *-5.00 FL 12 1 *REAR TAILGATE EMBLEM Serviceable 65.00 FL *-5.1 13 1 *REAR TAILGATE HYBRID LOGO Serviceable 68.00 FL *-5.1 14 1 *REAR TAILGATE HYBRID LOGO Serviceable 68.00 FL *-5.1 15 1 *QUARTER GLASS MOULDING Serviceable 198.00 FL *-5.1 15 1 *REAR FENDER LH Repair 89.00 FL *-5.1 16 1 *REAR FENDER INNERSHIELD LH Serviceable 212.00 FL *-5.1 18 1 *REAR FENDER INNER TRIM LH <t< td=""><td>5</td><td>1</td><td></td><td>*REAR BUMPER LOWER</td><td>Scratched</td><td>351.00 FL</td><td>*351.00 FL</td></t<> | 5 | 1 | | *REAR BUMPER LOWER | Scratched | 351.00 FL | *351.00 FL | |
| 8 1 *REAR BUMPER SPONGE Serviceable 187.00 FL *-FL 9 1 *REAR TAILLAMP LH Crumpled 498.00 FL *498.00 FL 10 1 *REAR TAILLAMP LOWER BRACKET LH Broken 85.00 FL *85.00 FL 11 1 *REAR TAILLAMP LOWER PANEL LH Repair 298.00 FL *-FL 12 1 *REAR TAILGATE EMBLEM Serviceable 65.00 FL *-FL 13 1 *REAR TAILGATE LOGO Serviceable 68.00 FL *-FL 14 1 *REAR TAILGATE HYBRID LOGO Serviceable 68.00 FL *-FL 15 1 *QUARTER GLASS MOULDING Serviceable 198.00 FL *-FL 15 1 *QUARTER GLASS MOULDING Serviceable 212.00 FL *-FL 16 1 *REAR FENDER INNERSHIELD LH Repair 898.00 FL *-FL 17 1 *REAR FENDER INNERSHIELD LH Serviceable 212.00 FL *-FL 18 1 *REAR FENDER INNER TRIM LH < | 6 | 1 | | *REAR BUMPER REFLECTOR LH | Cracked | 112.00 FL | *112.00 FL | |
| Total Parts (\$\$\frac{9}{2}\$ \$\$\frac{1}{2}\$ \$\frac{1}{2}\$ \$\ | 7 | 1 | | *REAR BUMPER REINF | Serviceable | 398.00 FL | *- FL | |
| Total Parts (\$\$) Total Parts (\$\$) \$4,631.25 1,440.75 | 8 | 1 | | *REAR BUMPER SPONGE | Serviceable | 187.00 FL | *- FL | |
| 11 | 9 | 1 | | *REAR TAILLAMP LH | Crumpled | 498.00 FL | *498.00 FL | |
| 12 | 10 | 1 | | *REAR TAILLAMP LOWER BRACKET LH | Broken | 85.00 FL | *85.00 FL | |
| 13 | 11 | 1 | | *REAR TAILLAMP LOWER PANEL LH | Repair | 298.00 FL | *- FL | |
| 14 | 12 | 1 | | *REAR TAILGATE EMBLEM | Serviceable | 65.00 FL | *- FL | |
| 15 | 13 | 1 | | *REAR TAILGATE LOGO | Serviceable | 62.00 FL | *- FL | |
| 16 1 *REAR FENDER LH Repair 898.00 FL *-FL 17 1 *REAR FENDER INNERSHIELD LH Serviceable 212.00 FL *-FL 18 1 *REAR END PANEL Repair 651.00 FL *-FL 19 1 *REAR END PANEL TOP GAR Serviceable 212.00 FL *-FL 20 1 *REAR FENDER INNER TRIM LH Serviceable 412.00 FL *-FL 21 1 *REAR FENDER AIR VENT LH Crumpled 72.00 FL *72.00 FL 22 1 *SET REAR BUMPER CLIP Necessary 50.00 FS *30.00 FS 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 50.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. <td>14</td> <td>1</td> <td></td> <td>*REAR TAILGATE HYBRID LOGO</td> <td>Serviceable</td> <td>68.00 FL</td> <td>*- FL</td> | 14 | 1 | | *REAR TAILGATE HYBRID LOGO | Serviceable | 68.00 FL | *- FL | |
| 17 1 *REAR FENDER INNERSHIELD LH Serviceable 212.00 FL *-FL 18 1 *REAR END PANEL Repair 651.00 FL *-FL 19 1 *REAR END PANEL TOP GAR Serviceable 212.00 FL *-FL 20 1 *REAR FENDER INNER TRIM LH Serviceable 412.00 FL *-FL 21 1 *REAR FENDER AIR VENT LH Crumpled 72.00 FL *72.00 FL 22 1 *SET REAR BUMPER CLIP Necessary 50.00 FS *30.00 FS 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (S\$) 1 | 15 | 1 | | *QUARTER GLASS MOULDING | Serviceable | 198.00 FL | *- FL | |
| 18 1 *REAR END PANEL Repair 651.00 FL *-FL 19 1 *REAR END PANEL TOP GAR Serviceable 212.00 FL *-FL 20 1 *REAR FENDER INNER TRIM LH Serviceable 412.00 FL *-FL 21 1 *REAR FENDER AIR VENT LH Crumpled 72.00 FL *72.00 FL 22 1 *SET REAR BUMPER CLIP Necessary 50.00 FS *30.00 FS 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (S\$) 1,443.75 470.25 | 16 | 1 | | *REAR FENDER LH | Repair | 898.00 FL | *- FL | |
| 19 | 17 | 1 | | *REAR FENDER INNERSHIELD LH | Serviceable | 212.00 FL | *- FL | |
| 20 1 *REAR FENDER INNER TRIM LH Serviceable 412.00 FL *-FL 21 1 *REAR FENDER AIR VENT LH Crumpled 72.00 FL *72.00 FL 22 1 *SET REAR BUMPER CLIP Necessary 50.00 FS *30.00 FS 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS 27 *-FS 28 *-FS 29 *-FS 29 *-FS 20 *-FS 20 *-FS 21 *-FS 22 *-FS 23 *-FS 24 *-FS 25 *-FS 26 *-FS 26 *-FS 27 *-FS 28 *-FS 29 *-FS 29 *-FS 20 *-FS 20 *-FS 20 *-FS 20 *-FS 20 *-FS 20 *-FS 21 *-FS 22 *-FS 23 *-FS 24 *-FS 25 *-FS 26 *-FS 26 *-FS 27 *-FS 28 *-FS 29 *-FS 20 *-FS 21 *-FS 22 *-FS 23 *-FS 24 *-FS 25 *-FS 26 *-FS 26 *-FS 27 *-FS 28 *-FS 29 *-FS 20 | 18 | 1 | | *REAR END PANEL | Repair | 651.00 FL | *- FL | |
| 21 1 *REAR FENDER AIR VENT LH Crumpled 72.00 FL *72.00 FL 22 1 *SET REAR BUMPER CLIP Necessary 50.00 FS *30.00 FS 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 | 19 | 1 | | *REAR END PANEL TOP GAR | Serviceable | 212.00 FL | *- FL | |
| 22 1 *SET REAR BUMPER CLIP Necessary 50.00 FS *30.00 FS 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 20 | 1 | | *REAR FENDER INNER TRIM LH | Serviceable | 412.00 FL | *- FL | |
| 23 1 *SET REAR FENDER INNERSHIELD CLIP Serviceable 50.00 FS *-FS 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 21 | 1 | | *REAR FENDER AIR VENT LH | Crumpled | 72.00 FL | *72.00 FL | |
| 24 1 *SET REAR END PANEL TOP GAR CLIP Serviceable 30.00 FS *-FS 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 22 | 1 | | *SET REAR BUMPER CLIP | Necessary | 50.00 FS | *30.00 FS | |
| 25 1 *REAR END PANEL SEALANT Serviceable 120.00 FS *-FS 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 23 | 1 | | *SET REAR FENDER INNERSHIELD CLIP | Serviceable | 50.00 FS | *-FS | |
| 26 1 *SET REAR FENDER INNERTRIM CLIP Serviceable 50.00 FS *-FS F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 24 | 1 | | *SET REAR END PANEL TOP GAR CLIP | Serviceable | 30.00 FS | *-FS | |
| F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 25 | 1 | | *REAR END PANEL SEALANT | Serviceable | 120.00 FS | *-FS | |
| Sub Total (\$\$) 6,075.00 1,911.00 - List Item Discount on L Items 25.00/25.00% (\$\$) 1,443.75 470.25 Total Parts (\$\$) 4,631.25 1,440.75 | 26 | 1 | | *SET REAR FENDER INNERTRIM CLIP | Serviceable | 50.00 FS | *-FS | |
| - List Item Discount on L Items 25.00/25.00% (S\$) 1,443.75 470.25 Total Parts (S\$) 4,631.25 1,440.75 | F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | | |
| Total Parts (S\$) 4,631.25 1,440.75 | | | | | V 17 | • | • | |
| | - List Item Discount on L Items 25.00/25.00% (S\$)1,443.75 470.2 | | | | | | 470.25 | |
| Report was unsubmitted during this print-out. | | | | | Total Parts (S\$) | 4,631.25 | 1,440.75 | |
| | Г | Report was unsubmitted during this print-out. | | | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount | | | | |
|-----|----------------------|-------------------------|------------|--------|--|--|--|--|
| Lab | <u>Labour Items</u> | | | | | | | |
| 1 | CHECK WIRING | New | 80.00 | 30.00 | | | | |
| 2 | ANTI RUST COAT | New | 150.00 | 40.00 | | | | |
| 3 | R+R REVERSE SENSOR | New | 120.00 | 30.00 | | | | |
| 4 | PANEL BEAT | New | 1,000.00 | 400.00 | | | | |
| 5 | SPRAY REAR FENDER LH | New | 800.00 | 400.00 | | | | |
| | | Gross Labour Cost (S\$) | 2,150.00 | 900.00 | | | | |

< END OF ESTIMATES >

Report was unsubmitted during this print-out.