



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000		Cust No/Name	KCV15434/NG HWEI BENG KATRINA
		Reg No/Reg Date	SMS3678X*# / 24/02/202
		Date In/Mileage	/ 12845
		Chassis No	MMBSTA13AKH003661
		Engine No	3A92UJC4890
		Make/Model	MIT/19MY ATTRAGE 1.2 CVT
		Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/10/2020/ 16:16	BLE	261 / Edwin Caina	58825

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER, BOOTLID & RR END PNL REPAIR RR FLR PNL, LHR FENDER & RHR FENDER @ 450 X 5				2250 2700.00
E PNT98000	RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER & RHR FENDER @ 350 X 1.5				2215 2450.00
E PNT88000	REMOVE & REFIT BOOTLID COMPONENT				120.00
E PNT88000	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET				120.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00
M SUNDRY	USING HI-SCAN PRO TEST				
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				40 80.00
M SUNDRY	SUPPLY RR NUMBER PLATE WITH CASING				50 X 50.00
E PNT88000	TO RENEW REVERSE SENSOR				60.00
M SUNDRY	TO SUPPLY REVERSE SENSOR				220.00
M SUNDRY	SUPPLY C&C BADGE				40.00
M SUNDRY	Sundries				20.00
M	FACE, RR BUMPER de 1.5xw	1.00	748.00	23.00	575.96
M	BRACKET, RR BUMPER, LH 1.5xw	1.00	28.00	23.00	21.56
M	BRACKET, RR BUMPER, RH 1.5xw	1.00	28.00	23.00	21.56
M	CLIP, RR BUMPER ne	4.00	4.00	23.00	12.32
M	UNPAINTED BODYKITS OR	1.00	1643.00	20.00	1643 1314.40
M	PANEL, RR END H	1.00	425.00	23.00	327.25

**Estimate**  
HI-SCAN PRO TEST

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

GST Reg No : MR-8500111-X

**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	KCV15434/NG HWEI BENG KATRINA
MOTOR CLAIM DEPARTMENT		Reg No/Reg Date	SMS3678X*# / 24/02/202
78 SHENTON WAY #08-16		Date In/Mileage	/ 12845
AIG BUILDING		Chassis No	MMBSTA13AKH003661
SINGAPORE 079120		Engine No	3A92UJC4890
Contact No 64191000		Make/Model	MIT/19MY ATTRAGE 1.2 CVT
		Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	23/10/2020/ 16:16	BLE	261 / Edwin Caina	58825				
Description of Goods / Services									
M	TRIM,RR END	du			1.00	66.00	23.00	Amount	50.82
M	BOARD,TRUNK ROOM FLOOR	ca 1.5cm			1.00	195.00	23.00	150.15	
M	COVER,RR VENTILATOR	ca 1.5cm			1.00	40.00	23.00	30.80	
M	DUCT,RR VENTILATOR	1.5vc			1.00	30.00	23.00	23.10	
M	BUZZER,KEYLESS OPERATIO,RR	ca 1.5cm			1.00	91.00	23.00	70.07	
M	ANT,KEYLESS OPERATION,RR	1.5vc			1.00	96.00	23.00	73.92	
M	PANEL,TRUNK LID	1.5vc			1.00	791.00	23.00	609.07	
M	WEATHERSTRIP,TRUNK LID	1.5vc			1.00	157.00	23.00	120.89	
M	HINGE,TRUNK LID,LH	X 5vc			1.00	203.00	23.00	156.31	
M	HINGE,TRUNK LID,RH	X 5vc			1.00	203.00	23.00	156.31	
M	LATCH,TRUNK LID	1.5vc			1.00	218.00	23.00	167.86	
M	STRIKER,TRUNK LID LATCH	X 5vc			1.00	20.00	23.00	15.40	
M	MARK,THREE-DIA	ca 1.5vc			1.00	69.00	23.00	53.13	
M	LAMP ASSY,COMB,RR LH	1.5vc			1.00	21.00	23.00	16.17	
M	LAMP ASSY,COMB,RR RH	1.5vc			1.00	335.00	23.00	257.95	
M	DECAL,MIVEC	ca 1.5vc			1.00	335.00	23.00	257.95	
					1.00	36.00	23.00	27.72	

Estimate

SURVEYOR NAME : Rahul - 4p 20010088  
 SURVEYOR SIGNATURE : [Signature]  
 DATE : 26/10/2020 @ 1030  
 REMARKS : 10 days  
excess: TDA/Repair  
Repair before paint

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Confirm & accepted by	7% GST on	10520.67	Nett	10,520.67
Authorized signatory and company stamp	Total Payable			736.45
				11,257.12

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windshield in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windshield.