

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011466/R1VF3E2

Date: 19/11/2020

REFERENCE

Insured/Claimant:	NG HWEE BENG KATRINA	Policy No:	2070013973
Date of Loss:	23/10/2020	Nature of Claim:	OD Claim No: 6122503457SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3678X	Engine No:	3A92UJC4890
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH003661
Reg. Date:	24/02/2020 (Man. Year: 2019)	Odometer:	12845 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,238.57	3,915.76	1,322.81	25.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	5,015.00	665.00	11.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,918.57	8,930.76	1,987.81	18.21
+ GST 7.00/7.00% (S\$)	764.30	625.15	139.15	18.21
Nett Amount (S\$)	11,682.87	9,555.91	2,126.96	18.21

INSPECTION

Date of Assignment:	23/10/2020	
Date Inspected:	26/10/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR NUMBER PLATE WITH CASING	Serviceable	50.00 FS	*- FS
2	1		*REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
3	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
4	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
5	1		*FACE, RR BUMPER	Deformed	748.00 FL	*748.00 FL
6	1		*BRACKET, RR BUMPER, LH	Serviceable	28.00 FL	*- FL
7	1		*BRACKET, RR BUMPER, RH	Serviceable	28.00 FL	*- FL
8	4		*CLIP, RR BUMPER	Necessary	16.00 FL	*16.00 FL
9	1		*UNPAINTED BODYKITS	Cracked	1,643.00 FS	*1,643.00 FS
10	1		*PANEL, RR END	Bent	425.00 FL	*425.00 FL
11	1		*TRIM, RR END	Deformed	66.00 FL	*66.00 FL
12	1		*BOARD, TRUNK ROOM FLOOR	Cracked	195.00 FL	*195.00 FL
13	1		*COVER, RR VENTILATOR	Cracked	40.00 FL	*40.00 FL
14	1		*DUCT, RR VENTILATOR	Serviceable	30.00 FL	*- FL
15	1		*BUZZER, KEYLESS OPERATIO, RR	Cracked	91.00 FL	*91.00 FL
16	1		*ANT, KEYLESS OPERATION, RR	Serviceable	96.00 FL	*- FL
17	1		*PANEL, TRUNK LID	Bent	791.00 FL	*791.00 FL
18	1		*WEATHERSTRIP, TRUNK LID	Serviceable	157.00 FL	*- FL
19	1		*HINGE, TRUNK LID, LH	Serviceable	203.00 FL	*- FL
20	1		*HINGE, TRUNK LID, RH	Serviceable	203.00 FL	*- FL
21	1		*LATCH, TRUNK LID	Serviceable	218.00 FL	*- FL
22	1		*STRIKER, TRUNK LID LATCH	Serviceable	20.00 FL	*- FL
23	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
24	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
25	1		*LAMP ASSY, COMB, RR LH	Serviceable	335.00 FL	*- FL
26	1		*LAMP ASSY, COMB, RR RH	Serviceable	335.00 FL	*- FL
27	1		*DECAL, MIVEC	Necessary	36.00 FL	*36.00 FL
28	1		*HARNES,RR END	Cut	90.00 FL	*90.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,214.00	4,511.00
- List Item Discount on L Items 23.00/23.00% (S\$)	975.43	595.24
Total Parts (S\$)	5,238.57	3,915.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, BOOTLID & RR END PNL REPAIR RR FLR PNL, LHR FENDER & RHR FENDER	New	2,700.00	2,250.00
2	RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER & RHR FENDER	New	2,450.00	2,275.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
8	TO RENEW REVERSE SENSOR	New	60.00	60.00
Gross Labour Cost (S\$)			5,680.00	5,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >