

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011468/UPS3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800004718

Claimant
Vehicle No : GBD8166H **Insured Vehicle No :** SLV9032R

Date of Loss: 21/10/2020 Nature of Claim: TP Claim No: 3075818415SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD8166H		
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Engine No:	1KD2463685
Reg. Date:	21/05/2015 (Man. Year: 2014)	Chassis No:	KDY2318017957
Colour:	Silver	Odometer:	151337 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	145 R13 (D)
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6/6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,393.50	3,878.60	7,514.90	65.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,380.00	1,390.00	50.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	14,163.50	5,258.60	8,904.90	62.87
Approved Total (Overridden) (\$)		4,200.00		
(\$)	14,163.50	4,200.00	9,963.50	70.35
+ GST 7.00/7.00% (\$)	991.45	294.00	697.45	70.35
Nett Amount (\$)	15,154.95	4,494.00	10,660.95	70.35
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 23/10/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Badly Dented	2,455.10 F	*1,455.10 FL
2	1		*FRONT DOOR SIGNAL LAMP O/S	Scratched	280.50 F	*135.20 FL
3	1		*FRONT DOOR HINGES	Lower Bent	210.00 F	*105.00 FL
4	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	288.50 F	*- FL
5	1		*FRONT DOOR INNER LOCK O/S	Not Necessary	299.30 F	*- FL
6	1		*FRONT DOOR INNER TRIM BOARD O/S	Not Necessary	645.20 F	*- FL
7	1		*FRONT STEP PANEL O/S	Repair	366.20 F	*- FL
8	1		*FRONT STEP GARNISH O/S	Damaged	322.50 F	*288.50 FL
9	1		*FRONT BUMPER	Distorted	781.10 F	*691.20 FL
10	1		*FRONT BUMPER FOG LAMP O/S	Cracked	450.00 F	*388.20 FL
11	1		*FRONT BUMPER FOG LAMP COVER O/S	Damaged	125.00 F	*105.10 FL
12	1		*FRONT BUMPER BRACKET O/S	Bent	250.50 F	*175.20 FL
13	1		*HEADLAMP O/S	Cracked	1,200.10 F	*922.10 FL
14	1		*FRONT GRILLE	Cracked	815.30 F	*475.20 FL
15	1		*FRONT GRILLE LOGO	Necessary	68.50 F	*68.50 FL
16	1		*CORNER PANEL O/S	Dented	322.50 F	*295.50 FL
17	1		*FRONT DOOR PILLAR O/S	Repair	988.10 F	*- FL
18	1		*FRON PANEL	Not Necessary	1,455.10 F	*- FL
19	1		*FRONT DOOR ROC STICKER O/S (1SET)	Necessary	50.00 FS	*30.00 FS
20	1		*HEADLAMP CLIP O/S (1SET)	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,393.50	5,154.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,276.20
Total Parts (\$\$)	11,393.50	3,878.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	60.00	50.00
3	TO TRANSFER FRONT DOOR MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	100.00	0.00
5	TO DISMANTLE & REFIX FRONT DASHBOARD	New	280.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	550.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	700.00
Gross Labour Cost (\$\$)			2,770.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >