

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011469/EPA3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900250282

Claimant
Vehicle No : GBK4739U **Insured Vehicle No :** SMQ5841M

Date of Loss: 21/10/2020 Nature of Claim: TP Claim No: 6136163738SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4739U		
Make & Model:	NISSAN NV350, 2.5 (A)	Engine No:	YD25068203B
Reg. Date:	11/08/2020 (Man. Year: 2019)	Chassis No:	JN1MC2E26Z0032063
Colour:	Silver	Odometer:	8030 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,955.52	1,537.62	3,417.90	68.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,849.00	1,470.00	1,379.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,804.52	3,007.62	4,796.90	61.46
Approved Total (Overridden) (\$\$)		2,400.00		
(\$\$)	7,804.52	2,400.00	5,404.52	69.25
+ GST 7.00/7.00% (\$\$)	546.32	168.00	378.32	69.25
Nett Amount (\$\$)	8,350.84	2,568.00	5,782.84	69.25
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 18/11/2020 Inspected At:

Efficient Motor & Engineering Works
Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang
Enterprise Building
Singapore 508775

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP LH	Not Necessary	209.80 FL	*- FL
2	1		*REAR BUMPER	Repair	600.50 FL	*- FL
3	3		*REAR BUMPER SIDE CLIP LH	Not Necessary	45.00 FL	*- FL
4	1		*REAR FENDER LH	Repair	2,010.20 FL	*- FL
5	1		*REAR FENDER MUDGUARD LH	Not Necessary	131.67 FL	*- FL
6	1		*LH SLIDE DOOR	Dented	1,497.70 FL	*1,497.70 FL
7	1		*LH SLIDE DOOR ROLLER LOWER	Not Necessary	112.70 FL	*- FL
8	1		*LH SLIDE DOOR WEATHERSTRIP	Not Necessary	187.80 FL	*- FL
9	1		*LH REAR WHEEL HUB CAP	Cut	177.43 FL	*177.43 FL
10	1		*SEALANT	Necessary	80.00 FS	*30.00 FS
11	1		*TYRE	Not Necessary	150.00 FS	*- FS
12	1		*RIM	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,452.80	1,705.13
- List Item Discount on L Items 10.00/10.00% (\$\$)	497.28	167.51
Total Parts (\$\$)	4,955.52	1,537.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT/WELD REAR FENDER,PANEL BEAT & INNER PANEL,REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	400.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	150.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO SPRAY PAINTING FOR REAR LH PORTIONS & AFFECTED AREAS	New	1,000.00	600.00
5	TO DO WHEEL ALIGNMENT AND TYRE BALANCING	New	150.00	60.00
6	TO REMOVE & TRANSFER DOOR COMPONENTS	New	149.00	50.00
7	TO DO COMPANY STICKER	New	350.00	300.00
Gross Labour Cost (\$\$)			2,849.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >