Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III20011470/R1PA3Q2 Our File No:

Date: 13/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015 Claimant SCP5555M Insured Vehicle No: SHC1642E

Vehicle No:

Date of Loss: Nature of Claim: TP 17/10/2020 Claim No: MCT20100276

DESCRIPTION & IDENTIFICATION OF VEHICLE

SCP5555M Reg No:

Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4027949 Reg. Date: 30/12/2015 (Man. Year: 2015) Chassis No: RU11107948 Colour: Odometer: 274397 km White

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Rear Left Side: Front Left Side: Bridgestone 5 mm Bridgestone 5 mm Rear Right Side: Front Right Side: Bridgestone 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,747.54	1,559.48	188.06	10.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	900.00	300.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,947.54	2,459.48	488.06	16.56
Approved Total (Overridden) (S\$)		1,950.00		
Nett Amount (S\$)	2,947.54	1,950.00	997.54	33.84
+ Loss of Use (4.0 x S\$80.00/day) (S		320.00		
Ne	tt Liability (S\$)	2,270.00		

INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 23/10/2020 Inspected At: Zenith Daniel Auto Services (HQ)

ZENITH DANIEL AUTO SERVICES, BLK 1009 BUKIT MERAH LANE 3 #01-96 SINGAPORE 159723

Singapore 159722

Estimated Period of Repair: 4.0 days

Manager: CHEW HSIAO TONG Adjuster: MOHD RASUL

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 04 Dec 2020)		
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SCP5555M)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR	Bent	950.00 FL	*950.00 FL
2	1		*REAR RIGHT DOOR	Bent	930.60 FL	*930.60 FL
3	1		*REAR RIGHT DOOR W/STRIP	Cut	55.00 FS	*55.00 FS
F=Fra	ınchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	1,935.60	1,935.60
- List Item Discount on L Items 10.00/20.00% (S\$)		188.06	376.12			
				Total Parts (S\$)	1,747.54	1,559.48
_						

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE FRONT RIGHT DOOR & TRANSFER DOOR MECHANISM TO NEW & REALIGN	New	300.00	200.00
2	TO REMPOVE REAR RIGHT DOOR & TRANSFER DOOR MECHANISM TO NEW & REALIGN	New	300.00	200.00
3	TO RESPRAY FRONT RIGHT DOOR & REAR RIGHT DOOR	New	600.00	500.00
	Gross Labour Cost (S\$)		1,200.00	900.00
	Report was unsubmitted durin	a this print-out		

< END OF ESTIMATES >