



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2008584

INV Date 29/12/2020

Reference CC4/FCI20011472/Ags3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJL 600L

Insured Veh. SHA 9484C

Claim No. D20004257MFSH

Policy No. D-20094921MFSH

Accident Date 23/10/2020

Inspection Date 23/10/2020

Description	Total
Survey Inspection	405.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	405.00
GST (7%)	28.35
Grand Total	433.35

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20011472/Ags3q2	
			Date: 29/12/2020	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9484C	Veh. Inspected	SJL 600L	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20004257MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	23/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2040452A350284	Colour	SILVER	
Odometer	222188 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2020	Inspection Date	23/10/2020	
Survey held at	KIANG MOTOR BLK 25 KAKI BUKIT ROAD 4 #08-26 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 600L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	1,350.00	1,350.00
1	BONNET INNER RUBBER	NOT NECESSARY	126.00	-
1	BONNET LOGO	NECESSARY	65.00	65.00
1	BONNET INNER LOCK	NOT NECESSARY	325.00	-
1	FRONT HEAD LAMP-LH	CRACKED	1,150.00	1,150.00
1	FRONT GRILLE EMBLE LOGO	NECESSARY	95.00	95.00
1	FRONT GRILLE	CRACKED	412.00	412.00
1	FRONT GRILLE GARNISH-CENTRE	NOT NECESSARY	155.00	-
1	FRONT GRILLE GARNISH-LOWER	NOT NECESSARY	258.00	-
1	FRONT BUMPER	DISTORTED	1,255.00	1,255.00
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
2	FRONT BUMPER SIDE BRACKET @\$65.00	N/S DAMAGED	130.00	65.00
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	122.00	-
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	FRONT BUMPER CENTER LOWER GARNISH	NOT NECESSARY	185.00	-
1	FRONT BUMPER SIDE FOG LAMP COVER-LH	DAMAGED	96.00	96.00
1	FRONT BUMPER SIDE FOG LAMP-LH	CRACKED	322.00	322.00
2	FRONT BUMPER SIDE LOWER MOUNTING @\$75.00	CUT	150.00	150.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	455.00	-
2	FRONT BUMPER REINFORCEMENT LOWER BRACKET @\$218.00	NOT NECESSARY	436.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	68.00	-
1	FRONT FENDER-LH	DISTORTED	821.00	821.00
1	FRONT FENDER INNER COWLING	TORN	155.00	155.00
1	FRONT L/H LOWER ARM	NOT NECESSARY	588.00	-
1	FRONT L/H KNUCKLE ARM	NOT NECESSARY	1,084.00	-
1	FRONT L/H KNUCKLE ARM BEARING	NOT NECESSARY	593.00	-
1	FRONT L/H TYRE	NOT NECESSARY	450.00	-
1	FRONT L/H RIM	NOT NECESSARY	650.00	-
	LESS 10% DISCOUNT		-	-596.60
			11,596.00	5,369.40

Report Ref No. CC4/FCI20011472/Ags3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TUFF KOTE.		120.00	50.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	REMOVE & REFIX FRONT LH UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	WHEEL ALIGNMENT (COMPUTER).	NOT NECESSARY	120.00	-
	PANEL BEATING.		1,000.00	700.00
	SPRAY PAINTING.		1,000.00	600.00
			2,570.00	1,380.00
	GRAND TOTAL		14,166.00	6,749.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,400.00

Report Ref No. CC4/FCI20011472/Ags3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 600L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 600L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

