

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20011473/UBA3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0000326
Claimant Vehicle No :	SGW6548T	Insured Vehicle No :	SKX4711Z
Date of Loss:	21/10/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002171

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW6548T	Engine No:	4G18JH1740
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A7U016354
Reg. Date:	26/07/2007 (Man. Year: 2007)	Odometer:	402840 km
Colour:	White		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	GREEN-MAX 5 mm	Rear Left Side:	GREEN-MAX 5 mm
Front Right Side:	GREEN-MAX 5 mm	Rear Right Side:	GREEN-MAX 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,073.00	4,085.80	6,987.20	63.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,180.00	2,200.00	50.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,453.00	6,265.80	9,187.20	59.45
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	15,453.00	5,000.00	10,453.00	67.64
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,257.45		
Global Sum Settlement (S\$)		5,200.00		

INSPECTION

Date of Assignment:	22/10/2020	
Date Inspected:	22/10/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2020)
Parts: 143	mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW6548T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	845.00 F	*684.00 FL
2	1		*BOOTLID OUTER GARNISH	Cracked	299.00 F	*197.00 FL
3	1		*BOOTLID INNER LOCK	Serviceable	195.00 F	*- FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	266.00 F	*166.00 FL
5	1		*BOOTLID REAR LOGO	Necessary	48.00 F	*48.00 FL
6	1		*BOOTLID MITSUBISHI EMBLEM	Necessary	60.00 F	*42.00 FL
7	1		*BOOTLID LANCER EMBLEM	Necessary	52.00 F	*45.00 FL
8	2		*BOOTLID HINGES	Not Necessary	330.00 F	*- FL
9	1		*REAR BUMPER	Deformed	801.00 F	*696.00 FL
10	1		*REAR BUMPER BEAM	Bent	195.00 F	*174.00 FL
11	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	130.00 F	*65.00 FL
12	1		*REAR BUMPER LOWER SKIRTING	Deformed / Torn	788.00 F	*681.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR END PANEL	Dented	580.00 F	*442.00 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	265.00 F	*161.00 FL
16	1		*REAR FLOOR PANEL	Repair	991.00 F	*- FL
17	1		*REAR FLOOR PANEL TOP BOARD	Torn	365.00 F	*175.00 FL
18	1		*TAILLAMPS	O/S Cracked	890.00 F	*404.00 FL
19	2		*REAR FENDERS	Repair	1,770.00 F	*- FL
20	1		*REAR FENDER INNER TRIMS	O/S Torn	732.00 F	*232.00 FL
21	1		*REAR EXHAUST	Not Necessary	580.00 F	*- FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	60.00 F	*- FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.00 F	*- FL
24	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
26	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Repeated	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,073.00	4,512.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	426.20
Total Parts (\$\$)	11,073.00	4,085.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (\$\$)			4,380.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >