

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011477/EPA3Q2

Date: 23/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2000002555

Claimant
Vehicle No : SJN6835B **Insured Vehicle No :** GBK1704P

Date of Loss: 21/10/2020 Nature of Claim: TP Claim No: 9655274624SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN6835B	Engine No:	1ZZ3230400
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W603002028
Reg. Date:	25/02/2009 (Man. Year: 2009)	Odometer:	263057 km
Colour:	Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50R15	Rear Tyre Size:	195/50R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,650.40	2,435.17	3,215.23	56.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,650.00	860.00	4,790.00	84.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,300.40	3,295.17	8,005.23	70.84
Approved Total (Overridden) (\$\$)		2,650.00		
Nett Amount (\$\$)	11,300.40	2,650.00	8,650.40	76.55
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,837.45		

INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 23/10/2020 Inspected At: Auburn Auto Pte Ltd (HQ)
176 SIN MING DRIVE, #04-18 SIN
MING AUTOCARE
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	180.00 F	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	380.00 F	*- FL
3	1		*FRONT BONNET INNER RUBBER	Not Necessary	68.20 F	*- FL
4	1		*FRONT BONNET OUTER RUBBER	Not Necessary	86.20 F	*- FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	135.90 F	*- FL
6	2		*FRONT BUMPER SIDE RETAINERS LH & RH	Broken	145.20 F	*145.20 FL
7	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	186.00 F	*- FL
8	1		*FRONT GRILLE CHROME MOULDING	Cut	285.90 F	*232.00 FL
9	1		*FRONT GRILLE LOGO	Necessary	188.80 F	*53.90 FL
10	1		*FRONT GRILLE	Broken	628.60 F	*117.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Broken	680.60 F	*680.60 FL
12	1		*FRONT BONNET LOCK	Not Necessary	380.00 F	*- FL
13	1		*CHROME TOYOTA LOGO	Not Necessary	135.00 F	*- FL
14	1		*L/H HEADLIGHT	Cut	1,220.00 F	*1,220.00 FL
15	1		*BONNET	Dented	950.00 F	*798.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,650.40	3,246.90
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	811.73
Total Parts (\$)	5,650.40	2,435.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSSING	New	320.00	30.00
2	TO APPLY TUFF KOTE	New	330.00	30.00
3	PANEL BEATING	New	2,800.00	400.00
4	TO SAND-DOWN,PATCH-WORK,RE-SPRAY PAINT	New	2,200.00	400.00
Gross Labour Cost (\$\$)			5,650.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >