

ASS. REC. BY:

Steve

REF:

CC4/AIG20011477/PA3

ASSIGNMENT

25/12/99

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJN 6835B

Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

c.c

Colour:

Blue

A/C:

Insured / Std / NI / N

Sp. Reading

263057

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

Gen. Cond: Good (Fair) Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

L/Bal.

5

mm

L/Bal.

5

D.O.A.

21/10/20

D.O.A.

23/10/20

Survey held at

Auburn

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MIV - 26K

Date/Time, File Pass to?

☐

: Prelim. Report

1)

Date/Time, File Return to?

☐

: Final Report

Rep. Form:

Lump Sum / L.B. / C.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Invs

(\$

☐

: Weekend

(\$

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: S.JN6835B

Model: Toyota Wish

QTY	Description	Repairer's Estimate	
Spare Parts - List Items			
1	Front bumper side grille X	\$	180.00
1	Front bonnet lock X	\$	380.00
1	Front bonnet inner rubber X	\$	68.20
1	Front bonnet outer rubber X	\$	86.20
1	Front bumper inner sponge X	\$	135.90
1	Front bumper side retainers / BR (LH & RH)	\$	145.20 /
1	Front headlamp lower bracket X	\$	186.00
1	Front grille chrome moulding (Bonnet garnish) / CNT	\$	285.90 232 /
1	Front grille logo / NK	\$	188.80 53.90 /
1	Front grille / BR	\$	628.60 117.20 /
2 /	Front bumper reinforcement (Front Bumper) / ? / BR	\$	680.60 /
1	Front bonnet lock X	\$	380.00
1	Chrome "Toyota" logo X	\$	135.00
1	L/H Headlight / CNT	\$	1,220.00 /
1	Bonnet / DD	\$	950.00 798 /
		\$	5,650.40

c/f: \$ 5,650.40

S.N.	Labour Charges		
1	To check wiring and reset headlamps focussing.	\$ 30	320.00
2	To apply tuff kote.	\$ 30	330.00
3	Panel beating.	\$ 400	2,800.00
4	To sand-down, patch-work, re-spray paint.	\$ 400	2,200.00
		\$	5,650.00

Total Repair Cost: \$ 11,300.40

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve
(Contact) 83228813
(Email) _____
(Signature) 
(Date/Time) 23/10/10, 1.30 pm

W1 A/L
3 dys
L/S

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: