

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20011479/DBS3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0005664

Claimant Vehicle No : SHD6570R**Insured Vehicle No :**

GBC7814H

Date of Loss: 20/10/2020

Nature of Claim:

TP

Claim No:

MFL2020D0002152

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD6570R**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDEU463232

Reg. Date: 09/04/2015 (Man. Year: 2015)

Chassis No:

KMHLB41UMFU067897

Colour: Blue

Odometer:

725971 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side:

Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side:

Hankook 5 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,088.00	7,077.08	5,010.92	41.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,740.00	1,690.00	3,050.00	64.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,828.00	8,767.08	8,060.92	47.90
Approved Total (Overridden) (S\$)		7,000.00		

(S\$)	16,828.00	7,000.00	9,828.00	58.40
+ GST 7.00/7.00% (S\$)	1,177.96	490.00	687.96	58.40
Nett Amount (S\$)	18,005.96	7,490.00	10,515.96	58.40
+ Loss of Use (8.0 x S\$40.00/day) (S\$)		320.00		
+ Car Rental (8.0 x S\$110.67/day) (S\$)		885.36		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		8,782.81		

INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 22/10/2020

Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6570R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,106.00 FL	*553.00 FL
2	1		*REAR BUMPER CLIP	Necessary	19.00 FL	*19.00 FL
3	1		*TAIL LAMP(LH)	Broken	697.80 FL	*697.80 FL
4	1		*TAIL LAMP QUARTER PANEL (LH)	Not Necessary	453.00 FL	*- FL
5	1		*REAR PANEL LOWER	Not Necessary	367.20 FL	*- FL
6	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	*- FL
7	1		*SPARE WHEEL LOCK NUT	Not Necessary	41.80 FL	*- FL
8	1		*SPARE TYRE PANEL	Not Necessary	852.80 FL	*- FL
9	1		*SPARE TYRE PANEL CUSHION	Not Necessary	223.10 FL	*- FL
10	1		*REAR FENDER	Dented	2,171.40 FL	*2,171.40 FL
11	1		*REAR FENDER UNDER SHIELD (LH)	Not Necessary	338.60 FL	*- FL
12	1		*FUEL LID COVER LH	Dislodged	82.10 FL	*82.10 FL
13	1		*FUEL LID GARNISH COVER	Broken	361.20 FL	*361.20 FL
14	1		*REAR TRAY LUGGS SIDE (LH)	Not Necessary	232.60 FL	*- FL
15	1		*REAR FENDER AIR-DUCT (LH)	Not Necessary	51.60 FL	*- FL
16	1		*REAR FENDER TRIM BOARD (LH)	Not Necessary	688.75 FL	*- FL
17	1		*REAR WINDSCREEN MOULDING	Necessary	51.80 FL	*51.80 FL
18	1		*REAR TYRE RIM (LH)	Bent	650.60 FL	*325.30 FL
19	1		*REAR TYRE WHEEL CAP	Broken	214.20 FL	*107.10 FL
20	1		*REAR WHEEL BEARING ING & HUB	Damaged	724.00 FL	*362.00 FL
21	1		*REAR TRAILING ARM (LH)	Distorted	384.00 FL	*192.00 FL
22	1		*REAR ASSIST (LH)	Distorted	219.40 FL	*145.70 FL
23	1		*REAR SHOCK ABSORBER (LH)	Distorted	683.70 FL	*276.30 FL
24	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	162.60 FL	*- FL
25	1		*ABS SENSOR	Not Necessary	217.90 FL	*- FL
26	1		*REAR CROSS MEMBER	Distorted	2,021.50 FL	*2,021.50 FL
27	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
29	1		*REAR UPPER ARM (LH)	Distorted	335.75 FL	*335.75 FL
30	1		*REAR LOWER ARM (LH)	Distorted	353.80 FL	*353.80 FL
31	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
32	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
33	1		*REAR FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
35	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,007.00	8,797.35
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,919.00	1,720.27
Total Parts (\$\$)	12,088.00	7,077.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	600.00
2	SPRAY PAINTING CHARGE	New	1,200.00	500.00
3	WIRING CHARGE	New	160.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
9	RE-SET REAR ABS SYSTEM	New	400.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (S\$)			4,740.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >